

September 18, 2017

[Redacted]

s.40(1)

Dear [Redacted]

s.40(1)

Re: Your request for access to information under Part II of the *Access to Information and Protection of Privacy Act* [Our File #: SNL-071-2017]

On August 18, 2017, Service NL received your requests for access to the following records:

"A complete list of stop-work orders to date for the Lower Churchill Project, including all sites (dam, transmission). Please note the date the order was issued and the reason for the order."

I am pleased to inform you that a decision has been made by Service NL to provide access to the requested information. In accordance with your request for a copy of the records, the appropriate copies have been enclosed. The attached list constitutes the record Service NL's Occupational Health and Safety Division has on file for Occupational Health and Safety orders for the Muskrat Falls hydroelectric development, the Labrador-Island Transmission Link, and the Maritime Link. This list identifies each visit made by the Division and the reason in accordance with the applicable section in the *Occupational Health and Safety Act* (the Act) and/or the *Occupational Health and Safety Regulations, 2012* (the Regulations). For example, if a visit resulted in a stop work order then this is noted in the list. Further to this, Service NL advises that you may wish to consider reviewing the attached list in conjunction with the Act and Regulations which can be found on the Government of Newfoundland and Labrador House of Assembly website via the following link:

<http://www.assembly.nl.ca/legislation/sr/titleindex.htm#O>.

Please be advised that you may ask the Information and Privacy Commissioner to review the processing of your access request, as set out in section 42 of the *Access to Information and Protection of Privacy Act* (the Act). A request to the Commissioner must be made in writing within 15 business days of the date of this letter or within a longer period that may be allowed by the Commissioner.

The address and contact information of the Information and Privacy Commissioner is as follows:

Office of the Information and Privacy Commissioner
2 Canada Drive
P. O. Box 13004, Stn. A
St. John's, NL. A1B 3V8

Telephone: (709) 729-6309
Toll-Free: 1-877-729-6309
Facsimile: (709) 729-6500

You may also appeal directly to the Supreme Court Trial Division within 15 business days after you receive the decision of the public body, pursuant to section 52 of the Act.

Please be advised that responsive records will be published following a 72 hour period after the response is sent electronically to you or five business days in the case where records are mailed to you. It is the goal to have the responsive records posted to the Completed Access to Information Requests website within one business day following the applicable period of time. Please note that requests for personal information will not be posted online.

If you have any further questions, please feel free to contact me by telephone at 709-729-7437 or by email at ellenhaskell@gov.nl.ca.

Sincerely,



ELLEN HASKELL
ATIPP Coordinator

INSPECTIONS AND ORDERS FROM JANUARY 1, 2012 - JULY 31, 2017

LOWER CHURCHILL PROJECT											
INSPECTION DATE	FIRM NAME	WORKSITE	WORKSITE ADDRESS	REASON	INSPECTION #	ORDER #	Occupational Health and Safety Act	ACT TEXT	Occupational Health and Safety Regulations	REGULATION TEXT	
2016/10/18	ABB INC.	Bottom Brook HVDC Converter Station	Maritime Link Project, NL.	Regular Inspection	671988	0					
2016/12/15	ABB INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941570	1			Part XXVI - Electrical Operations	478 1- -Electrical requirements	
2017/03/08	ABB INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941609	1	Occupational Health and Safety	26 - 1b -Powers of investigation			
2017/03/29	ABB INC.	Vault work/land cable terminations	Transition compound, Cape Ray, NL	Regular Inspection	941625	0					
2017/03/31	ABB INC.	Bottom Brook HVDC Converter Station	Maritime Link Project, NL.	Regular Inspection	941630	1			Part V - General Health & Safety Require	38 1- -Emergency plan risk assess	
2017/03/31	ABB INC.	Bottom Brook HVDC Converter Station	Maritime Link Project, NL.	Regular Inspection	941630	2	Occupational Health and Safety	5 - b -Specific duties of employers			
2017/03/31	ABB INC.	Bottom Brook HVDC Converter Station	Maritime Link Project, NL.	Regular Inspection	941630	3			OHS First Aid Regulations	5 3- -First Aid Room Required	
2017/04/05	ABB INC.	Building construction	Transition Compound, Cape Ray, NL	Regular Inspection	941636	0					
2017/04/11	ABB INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941644	1			Part V - General Health & Safety Require	36 1- -Illumination	
2017/04/11	ABB INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941644	2			Part V - General Health & Safety Require	36 1- -Illumination	
2015/05/13	AGF STEEL INC.	Lower Churchill Development	Happy Valley -Goose Bay, NL.	Regular Inspection	671755	1			Part XV - Rigging	364 - -Slings standards	
2015/08/04	AGF STEEL INC.	Lower Churchill Development	Happy Valley -Goose Bay, NL.	Regular Inspection	671793	0					
2016/03/04	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	770471	1			Part VI - Occupational Health Requirement	42 1- - Hazardous substances	
2016/03/04	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	770471	2			Part X - Fall Protection	146 -b -Temporary flooring	
2015/06/04	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010083	1			Part VII - Personal Protective Equipment	84 1- -Respiratory protection	
2015/06/04	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010083	2			Part VIII - Machinery and Equipment	88 1-b i -Safe machinery and equipment	
2015/06/04	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010083	3			Part VIII - Machinery and Equipment	89 -c -General requirements	
2015/07/02	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010084	1			Part XXVI - Electrical Operations	478 1- -Electrical requirements	
2015/07/02	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010084	2			Part V - General Health & Safety Require	36 2- -Illumination	
2015/08/14	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010088	0					
2015/10/09	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010101	0					
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	1			Part VI - Occupational Health Requirement	45 8- - Ventilation	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	2			Part XVII - Construction, Excavation & D	384 1- -Concrete placing hazards	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	3			Part XV - Rigging	355 - -Replacing pins	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	4			Part III - General Duties	16 2-a -Safe working load of equip	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	5			Part V - General Health & Safety Require	36 1- -Illumination	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	6			Part XII - Powered Mobile Equipment	268 - -Securing tools and equipment	
2015/11/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010108	7			Part XVIII - Excavation, Underground Work	407 2-b -Excavation or access	
2016/01/26	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010113	0					
2016/03/24	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Investigate Incident	1010118	0					
2016/06/30	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010123	1	Occupational Health and Safety	10 - -Duty of principal contractor			
2016/11/25	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010141	1			Part VI - Occupational Health Requirement	68 5- -Noise hazards	
2016/11/25	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010141	2			Part VIII - Machinery and Equipment	98 - -Rotating hazards	
2016/11/25	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010141	3			Part XXII - Access and Egress	458 2- -Access, egress and movement	
2017/03/17	ALSTOM POWER CANADA INC.	Site Development	Soldiers Pond, TCH East of Butterpot Park Interchange	Regular Inspection	1010148	0					
2014/04/10	AMEC FOSTER WHEELER	Lower Churchill Project	Muskrat Falls, NL	Hygiene Assessment	860236	1	Occupational Health and Safety	26 - 1b -Powers of investigation			
2016/10/27	AMEC FOSTER WHEELER	Powerline Transmission Project	Tower 370, Catamaran Access, West of Badger NL	Regular Inspection	951034	1			OHS First Aid Regulations	4 3- -Duties of employer	
2015/12/03	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671863	1			Part V - General Health & Safety Require	30 2- -Openings, pits and tanks	
2015/12/03	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671863	2			Part XVI - Traffic Control	373 2- -Traffic control	
2016/07/20	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671944	1			Part X - Fall Protection	146 -c -Temporary flooring	
2016/07/20	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671944	2			Part VIII - Machinery and Equipment	97 -a -Restraining devices	
2016/07/20	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671944	3			Part XXII - Access and Egress	458 2- -Access, egress and movement	
2016/09/14	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671969	1			Part IX - De-Energization and Lockout	128 - -General requirement	
2016/09/14	ANDRITZ HYDRO CANADA INC.	Muskrat Falls	Happy Valley-Goose Bay, NL.	Regular Inspection	671969	2			Part X - Fall Protection	142 5- -Fall arrest system	
2014/01/14	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671629	1			Part VIII - Machinery and Equipment	88 1-a -Safe machinery and equipment	
2014/01/14	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671629	2			Part XXVI - Electrical Operations	488 2- -Grounding portable low vol	
2014/01/14	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671629	3			Part XXII - Access and Egress	460 1-a -Stairs	
2014/03/05	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671643	1			Part XVI - Traffic Control	373 3- -Traffic control	
2014/03/05	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671643	2			Part XVI - Traffic Control	373 3- -Traffic control	
2014/03/05	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671643	3			Part XVI - Traffic Control	373 3- -Traffic control	
2014/07/08	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671669	0					
2014/08/12	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Complaint	671679	0					
2014/10/15	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671695	1	Occupational Health and Safety	54 - 1b -Reporting accidents			
2014/10/15	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671696	0					
2014/10/16	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671697	1	Occupational Health and Safety	27 - 1a -Stop work orders	Part III - General Duties	14 1- -General duties of employer	
2014/10/16	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671697	2			Part VIII - Machinery and Equipment	88 1-b i -Safe machinery and equipment	
2014/11/21	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671706	0					
2014/11/21	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Incident	671707	1			Part III - General Duties	12 1-d -Occupational health and safety	
2014/11/25	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671709	1			Part XXII - Access and Egress	458 2- -Access, egress and movement	
2014/11/25	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671709	2			Part VI - Occupational Health Requirement	68 1-a -Noise hazards	
2014/11/25	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671709	3			Part VI - Occupational Health Requirement	68 1-b -Noise hazards	
2014/11/25	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671709	4			Part VI - Occupational Health Requirement	42 1- -Hazardous substances	
2014/11/25	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671709	5			Part XXII - Access and Egress	458 1- -Access, egress and movement	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	1			Part V - General Health & Safety Require	38 2- -Emergency plan risk assess	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	2			Part V - General Health & Safety Require	41 1- -Emergency training	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	3			Part XX - Fire Prevention & Control	443 1- -Fire protection	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	4			Part V - General Health & Safety Require	28 6- -Guardrails	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	5			Part XXII - Access and Egress	458 2- -Access, egress and movement	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	6			Part VII - Occupational Health Requirement	67 -d -Sanitary and orderly conditions	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	7			Part XVII - Construction, Excavation & D	378 1-c -Protection from falling ma	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	8			Part XVII - Construction, Excavation & D	379 1- -Chutes	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	9			Part VII - Personal Protective Equipment	81 - -High visibility apparel	
2015/01/27	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671720	10			Part XI - Scaffolds, Stages & Work Platform	152 -b -Inclination and support	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	1			Part III - General Duties	12 1-c -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	2			Part III - General Duties	12 2-b iii -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	3			Part III - General Duties	12 1-e -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	4			Part III - General Duties	12 1-e -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	5			Part III - General Duties	12 1-e -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	6			Part III - General Duties	12 1-l -Occupational health and safety	
2015/02/23	ASTALDI CANADA	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Investigate Accident	671730	7			Part VII - Personal Protective Equipment	71 -b -Selection, use and maintenance	

2014/06/02	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Regular Inspection	671660	3			Part XII - Powered Mobile Equipment	269 -	-Unattended equipment	
2014/06/02	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Regular Inspection	671660	4			Part XIX - General Blasting	417 -o	-Definitions	
2014/07/02	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Investigate Incident	671665	0						
2016/02/18	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Investigate Incident	671886	1	Occupational Health and Safety	54 - 1b	-Reporting accidents			
2016/03/04	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	770470	0						
2014/08/01	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010058	0						
2014/08/25	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Investigate Incident	1010061	0						
2014/09/09	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Follow-up	1010064	0						
2014/10/02	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010070	0						
2015/05/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010080	1			Part XXXII - Open Cut Workings in Minin	655 -1-b	-Protective curbs or berms	
2015/05/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010080	2			Part VI - Occupational Health Requirement	63 -a	-Emergency washing facility	
2015/05/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010080	3			Part VI - Occupational Health Requirement	42 -1	-Hazardous substances	
2015/05/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010080	4			OHS First Aid Regulations	17 -	-#2 First Aid Kit	
2015/05/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010080	5			Part VI - Occupational Health Requirement	45 -2	-Ventilation	
2015/08/06	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010086	1			Part XXVI - Electrical Operations	488 -2	-Grounding portable low vol	
2015/08/14	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010089	1			Part XII - Powered Mobile Equipment	269 -	-Unattended equipment	
2015/09/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010099	1			Part XXVI - Electrical Operations	488 -2	-Grounding portable low vol	
2015/09/28	H.J. O'CONNELL CONSTRUCTION LIMITED	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010099	2			Part VI - Occupational Health Requirement	46 -3-c	-Silica regulation	
2016/03/07	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Investigate Incident	1010117	0						
2016/06/30	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010124	1			Part V - General Health & Safety Require	28 -6	-Guardrails	
2016/06/30	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010124	2			Part X - Fall Protection	141 -b & d -h	-General requirements	
2016/06/30	H.J. O'CONNELL CONSTRUCTION LIMITED	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010124	3			Part VI - Occupational Health Requirement	46 -5	-Silica regulation	
2017/07/19	HARBORSIDE GEOTECHNICAL CONSULTANTS	Access AT 229, near Structure SC091	Access AT 229, near Structure SC091	Regular Inspection	640938	1			OHS First Aid Regulations	4 -3	-Duties of employer	
2017/07/19	HI-VIS TRAFFIC CONTROL INC.	TCH - Divided Highway - West Lanes	Holyrood Access Area opposite entrance to Rod and Gun Club	Regular Inspection	640945	2	Occupational Health and Safety	26 - 2	-Powers of investigation			
2017/07/19	HI-VIS TRAFFIC CONTROL INC.	TCH - Divided Highway - West Lanes	Holyrood Access Area opposite entrance to Rod and Gun Club	Regular Inspection	640945	2	Occupational Health and Safety	26 - 2	-Powers of investigation			
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	1	Occupational Health and Safety	5 - a	-Specific duties of employers			
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	2			Part VII - Personal Protective Equipment	78 -	-General requirements of li	
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	3			Part VII - Personal Protective Equipment	78 -	-General requirements of li	
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	4			Part VII - Personal Protective Equipment	78 -	-General requirements of li	
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	5	Occupational Health and Safety	5 - a	-Specific duties of employers			
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	6	Occupational Health and Safety	5 - b	-Specific duties of employers			
2016/11/08	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	640938	7			Part VII - Personal Protective Equipment	74 -2	-General requirements of safety	
2016/12/01	HSE INTEGRATED LIMITED	Paramedic room	Camp site for Maritime Link Project, off Burgeo Highway, NL	Regular Inspection	931862	1			Part VI - Occupational Health Requirement	67 -d	-Sanitary and orderly conditions	
2016/12/01	HSE INTEGRATED LIMITED	Paramedic room	Camp site for Maritime Link Project, off Burgeo Highway, NL	Regular Inspection	931862	2			Part VI - Occupational Health Requirement	42 -4	-Hazardous substances	
2017/01/10	HSE INTEGRATED LIMITED	Paramedic room	Camp site for Maritime Link Project, off Burgeo Highway, NL	Regular Inspection	931891	0						
2017/03/22	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	951126	1			Part XX - Fire Prevention & Control	443 -1	-Fire protection	
2017/03/22	HSE INTEGRATED LIMITED	Emergency Transport Vehicle	Granite Canal Site	Regular Inspection	951126	2			Part III - General Duties	12 -1-e	-Occupational health and safety	
2013/01/16	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500936	1			Part XVI - Traffic Control	373 -2	-Traffic control	
2013/01/16	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500936	2			Part VII - Personal Protective Equipment	81 -	-High visibility apparel	
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	1	Occupational Health and Safety	26.2 -	-Requirement to provide assist			
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	2			Part XVIII - Excavation, Underground Work	413 -6	-Air quality	
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	3			Part XVIII - Excavation, Underground Work	409 -1-a	-Faces and slopes	
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	4			Part XX - Fire Prevention & Control	444 -5	-Fire and explosion	
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	5	Occupational Health and Safety	4 -	-Employers' general duty			
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	6			Part XXI - Welding, Burning & Cutting Op	440 -1-a ii	-Compressed gas cylinders	
2013/03/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	500951	7			Part XX - Fire Prevention & Control	453 -1	-Fire protection	
2013/06/13	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501007	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XXVIII - Excavation, Underground Work	413 -6	-Air quality
2013/06/13	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501007	2	Occupational Health and Safety	27 - 1a	-Stop work orders	Part VII - Personal Protective Equipment	84 -2	-Respiratory protection
2013/06/13	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501007	3			Part VII - Personal Protective Equipment	85 -1	-Respiratory protection equip	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	1			Part VII - Personal Protective Equipment	85 -5-a	-Respiratory protection equip	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	2			Part XXXII - Open Cut Workings in Minin	658 -	-Lifelines	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	3	Occupational Health and Safety	27 - 1a	-Stop work orders	Part III - General Duties	14 -4	-General duties of employer
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	4			Part XXXII - Open Cut Workings in Minin	663 -2	-Rotary drilling	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	5			Part XXXII - Open Cut Workings in Minin	655 -1-f	-Protective curbs or berms	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	6			Part XXXII - Open Cut Workings in Minin	655 -1-e i	-Protective curbs or berms	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	7			Part XXXIII - General Mining Requirement	530 -d	-Emergency stops,warning de	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	8			Part XXVI - Electrical Operations	481 -2	-Space around equipment	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	9			Part XXXII - Open Cut Workings in Minin	655 -1-d	-Protective curbs or berms	
2013/09/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	501037	10			Part XXVI - Electrical Operations	478 -1	-Electrical requirements	
2013/01/15	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671518	1			Part XII - Powered Mobile Equipment	266 -1	-Seating and standard requirement	
2013/01/15	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671518	2	Occupational Health and Safety	37 -	-Committees			
2013/01/15	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671518	3			Part III - General Duties	18 -1	-Safety inspections	
2013/01/15	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671518	4			Part III - General Duties	12 -1-g l	-Occupational health and safety	
2013/01/15	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671518	5			Part XXVI - Electrical Operations	488 -2	-Grounding portable low vol	
2013/04/24	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671541	1			Part XII - Powered Mobile Equipment	279 -4	-Equipment and procedures	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	1			Part IX - De-Energization and Lockout	130 -1	-Lockout procedures	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	2			Part XXVI - Electrical Operations	481 -1-b	-Space around equipment	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	3			Part XXI - Welding, Burning & Cutting Op	453 -4	-Burning and welding	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	4			Part VII - Personal Protective Equipment	85 -1	-Respiratory protection equip	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	5			Part XXI - Welding, Burning & Cutting Op	449 -1-a	-Gas welding and burning	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	6			Part VIII - Machinery and Equipment	88 -1-b i	-Safe machinery and equipment	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	7			Part XX - Fire Prevention & Control	444 -5	-Fire and explosion	
2013/06/18	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671549	8			Part VI - Occupational Health Requirement	63 -a	-Emergency washing facility	
2013/11/26	IKC-ONE	Site Development	Muskkrat Falls, NL	Regular Inspection	671606	0			Part XXXII - Open Cut Workings in Minin	655 -1-e ii	-Protective curbs or berms	
2015/01/28	INNU-MED INC.	Med Clinic, Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860319	1	Occupational Health and Safety	5 - a	-Specific duties of employers			
2016/02/18	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Investigate Incident	720073	1			Part III - General Duties	12 -1-g iv	-Occupational health and safety	
2016/02/18	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Investigate Incident	720073	2			Part V - General Health & Safety Require	31 -1	-Material storage	
2016/02/18	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Investigate Incident	720073	3			Part III - General Duties	18 -1	-Safety inspections	
2016/09/30	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010129	1			Part XI - Scaffolds, Stages & Work Platform	203 -1-a & b	-Operating and maintenance	
2016/09/30	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010129	2			Part XII - Powered Mobile Equipment	268 -	-Securing tools and equipment	
2016/09/30	INSULATED PANEL STRUCTURES INC.	Soliders Pond	TCH East of Butterpot Park Interchange	Regular Inspection	1010129	3			Part X - Fall Protection	141 -b & d -h	-General requirements	
2015/04/24	ISKUETEU, A LIMITED PARTNERSHIP	Muskkrat Falls Project	Happy Valley-Goose Bay, NL	Investigate Incident	671741	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part IX - De-Energization and Lockout	128 -	-General requirement
2015/04/24	ISKUETEU, A LIMITED PARTNERSHIP	Muskkrat Falls Project	Happy Valley-Goose Bay, NL	Investigate Incident	671741	2			Part XXVI - Electrical Operations	484 -1	-Low voltage-lockout	
2015/04/24	ISKUETEU, A LIMITED PARTNERSHIP	Muskkrat Falls Project	Happy Valley-Goose Bay, NL	Investigate Incident	671741	3			Part III - General Duties	12 -1-c	-Occupational health and safety	

2015/04/29	ISKUETEU, A LIMITED PARTNERSHIP	Muskat Falls Project	Happy Valley-Goose Bay, NL	Follow-up	671744	0				
2016/10/14	ISKUETEU, A LIMITED PARTNERSHIP	Muskat Falls Project	Happy Valley-Goose Bay, NL	Investigate Accident	671983	0				
2017/03/08	ISLAND DYNAMICS INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941603	1			Part VIII - Machinery and Equipment	89 -b - -General requirements
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	1			Part XII - Powered Mobile Equipment	267 1- -Start of shift inspection
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	2			Part VII - Personal Protective Equipment	81 - -High visibility apparel
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	3			Part VII - Personal Protective Equipment	75 - -Eye and face protection
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	4			Part VII - Personal Protective Equipment	74 1- -General requirements of safety
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	5			OHS First Aid Regulations	16 - -#1 First Aid Kit
2016/12/08	JEST CONST INC	Fill delivery	Structure 57, Doyleys, NL	Regular Inspection	941561	6			Part XII - Powered Mobile Equipment	251 6- -Operation and maintenance
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	1	Occupational Health and Safety	27 - 1b - -Stop work orders	Part VII - Machinery and Equipment	88 1-a - -Safe machinery and equipment
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	2			Part XII - Powered Mobile Equipment	267 1- -Start of shift inspection
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	3			Part VII - Personal Protective Equipment	75 - -Eye and face protection
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	4			Part VII - Personal Protective Equipment	74 1- -General requirements of safety
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	5			OHS First Aid Regulations	16 - -#1 First Aid Kit
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	6			Part VII - Personal Protective Equipment	81 - -High visibility apparel
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	7			Part XX - Fire Prevention & Control	444 4- -Fire and explosion
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	8			Part XII - Powered Mobile Equipment	251 6- -Operation and maintenance
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	9			Part XXXII - Open Cut Workings in Minin	655 1-b - -Protective curbs or berms
2016/12/08	JEST CONST INC	Site work	Doyleys, NL	Regular Inspection	941563	10			Part XII - Powered Mobile Equipment	251 1- -Operation and maintenance
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	1			Part XXVIII - General Mining Requirement	531 8- -Conveyors general requirement
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	2			Part XXXII - Open Cut Workings in Minin	655 1-e i - -Protective curbs or berms
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	3			255 1-a - -Warning signal device	
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	4			Part VII - Personal Protective Equipment	81 - -High visibility apparel
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	5			Part VI - Occupational Health Requirement	45 2- -Ventilation
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	6			Part XXVIII - General Mining Requirement	530 -d - -Emergency stops, warning de
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	7			Part XX - Fire Prevention & Control	443 1- -Fire protection
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	8			Part XXII - Access and Egress	460 1-a - -Stairs
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	9			Part XV - Rigging	353 1- -Open hook restriction
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	10			Part XV - Rigging	365 - -Inspection before use
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	11			Part XXVI - Electrical Operations	481 2- -Space around equipment
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	12			Part VI - Occupational Health Requirement	45 1-a - -Ventilation
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	13			Part XXXII - Open Cut Workings in Minin	662 3- -Ramps
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	14			Part XVIII - Excavation, Underground Work	409 1-b - -Faces and slopes
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	15			Part XXXII - Open Cut Workings in Minin	656 2- -Heights of faces and bench
2013/09/17	JOHNSON 'S CONSTRUCTION	Granite Quarry	South of Churchill River, TLH - South connection	Regular Inspection	501035	16			Part XII - Powered Mobile Equipment	251 1- -Operation and maintenance
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	1			Part XXXII - Open Cut Workings in Minin	658 - -Lifelines
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	2			Part XVIII - Excavation, Underground Work	409 1-b - -Faces and slopes
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	3			Part XII - Powered Mobile Equipment	255 1-a - -Warning signal device
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	4			Part XXXII - Open Cut Workings in Minin	672 1-a b&c - -Stockpiles
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	5			Part XIX - General Blasting	420 2-a & b - -Security and report requirement
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	6			Part XIX - General Blasting	431 1- -Preparing the blast loading
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	7			Part XIX - General Blasting	433 1- -Loaded holes
2013/11/26	JOHNSON 'S CONSTRUCTION	Quarry #1 - off access road to Site	Lower Churchill Falls Project - Happy Valley-Goose Bay, NL	Regular Inspection	501064	8			Part XIX - General Blasting	448 -a - -Employer's responsibility
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	1			Part XX - Fire Prevention & Control	413 1- -Fire protection
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	2			Part VI - Occupational Health Requirement	63 -a - -Emergency washing facility
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	3			Part V - General Health & Safety Require	36 1- -Illumination
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	4			Part V - Occupational Health Requirement	67 -a - -Sanitary and orderly conditions
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	5			Part XX - Fire Prevention & Control	444 5- -Fire and explosion
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	6			Part XV - Rigging	365 - -Inspection before use
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	7			Part XV - Rigging	353 1- -Open hook restriction
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	8			Workplace Hazardous Materials Information	9 1- -Decanted Products
2013/11/27	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	501067	9			Part VI - Occupational Health Requirement	45 4- -Ventilation
2014/10/14	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	501185	0				
2013/07/24	JOHNSON 'S CONSTRUCTION	Camp Entrance KM 64	Trans Labrador Highway, NL.	Regular Inspection	671554	0				
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	1			Part XV - Rigging	353 1- -Open hook restriction
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	2			Part VI - Occupational Health Requirement	42 1- -Hazardous substances
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	3			Part III - General Duties	14 1- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	4			Part V - General Health & Safety Require	40 1- -Emergency lighting
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	5			Part V - General Health & Safety Require	36 2- -Illumination
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	6			Part V - General Health & Safety Require	40 1- -Emergency lighting
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	7			Part V - Occupational Health Requirement	42 5- -Hazardous substances
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	8			Workplace Hazardous Materials Information	9 1- -Decanted Products
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	9			Part III - General Duties	14 1- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	10			Part XXVI - Electrical Operations	478 1- -Electrical requirements
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	11			Part III - General Duties	14 1- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	12			Part III - General Duties	14 1- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	13			Part III - General Duties	14 1- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	14			Part III - General Duties	14 4- -General duties of employer
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	15	Occupational Health and Safety	5 - a - -Specific duties of employers		
2014/01/15	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Regular Inspection	671632	16			Part XXII - Access and Egress	458 2- -Access, egress and movement
2014/03/05	JOHNSON 'S CONSTRUCTION	Main camp / Maintenance area	TLH, 67 kilometres West of Happy Valley-Goose Bay, NL	Follow-up	671644	1			Part XXVI - Electrical Operations	478 1- -Electrical requirements
2014/07/10	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671672	1			Part III - General Duties	12 1-e - -Occupational health and safety
2014/07/10	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671672	2			Part VI - Occupational Health Requirement	61 1- -Toilet facilities
2014/07/10	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671672	3			Part XVII - Access and Egress	458 1- -Access, egress and movement
2014/07/10	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671672	4			Part XX - Fire Prevention & Control	444 6- -Fire and explosion
2014/07/10	JOHNSON 'S CONSTRUCTION	Switch Yard Site Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671672	5			Part V - General Health & Safety Require	36 2- -Illumination
2014/08/13	JOHNSON 'S CONSTRUCTION	Reservoir Clearing	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671682	1			Part III - General Duties	12 1-e - -Occupational health and safety
2014/08/13	JOHNSON 'S CONSTRUCTION	Reservoir Clearing	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671682	2			Part VIII - Machinery and Equipment	88 2-a - -Safe machinery and equipment
2014/08/13	JOHNSON 'S CONSTRUCTION	Reservoir Clearing	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671682	3			Part XXXII - Diving & Other Marine Opera	465 1- -Floating work platforms
2014/08/13	JOHNSON 'S CONSTRUCTION	Reservoir Clearing	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671682	4			Part III - General Duties	14 1- -General duties of employer
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL.	Regular Inspection	671889	1			Part XXVI - Electrical Operations	481 1-a - -Space around equipment
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL.	Regular Inspection	671889	2			Part XX - Fire Prevention & Control	444 5- -Fire and explosion
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL.	Regular Inspection	671889	3			Part V - General Health & Safety Require	36 2- -Illumination
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL.	Regular Inspection	671889	4			Part III - General Duties	18 1- -Safety inspections
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL.	Regular Inspection	671889	5			Part V - General Health & Safety Require	36 5- -Illumination

2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL	Regular Inspection	671889	6			Part XVIII - Excavation, Underground Work	408 1-b	- Removal of material
2016/02/23	JOHNSON 'S CONSTRUCTION	Johnson's Construction Camp	KM 83 St. Paul River Road, NL	Regular Inspection	671889	7			Part V - General Health & Safety Require	39 3-	- Emergency procedures
2016/02/24	JOHNSON 'S CONSTRUCTION	DC Transmission Line	Lower Churchill Project, NL	Regular Inspection	671890	1			Part XII - Powered Mobile Equipment	257 1-	- Rear view mirrors
2016/02/24	JOHNSON 'S CONSTRUCTION	DC Transmission Line	Lower Churchill Project, NL	Regular Inspection	671890	2			Part VIII - Machinery and Equipment	88 1-b i	- Safe machinery and equipment
2016/02/24	JOHNSON 'S CONSTRUCTION	DC Transmission Line	Lower Churchill Project, NL	Regular Inspection	671890	3			Part VIII - Machinery and Equipment	110 5-	- Automotive lifts and vehicle
2016/10/26	JOHNSON 'S CONSTRUCTION	Reservoir Clearing	Edward's Brook Camp, Trans Labrador Highway, NL	Investigate Accident	671995	0					
2015/07/23	JOHNSON 'S CONSTRUCTION	Round Pond, PR 432	Plum Point, NL	Regular Inspection	901499	1			Part VI - Occupational Health Requirement	63 -a	- Emergency washing facility
2015/07/23	JOHNSON 'S CONSTRUCTION	Round Pond, PR 432	Plum Point, NL	Regular Inspection	901499	2			Part VI - Occupational Health Requirement	63 -a	- Emergency washing facility
2015/07/23	JOHNSON 'S CONSTRUCTION	Round Pond, PR 432	Plum Point, NL	Regular Inspection	901499	3			Part XV - Rigging	353 1-	- Open hook restriction
2015/07/23	JOHNSON 'S CONSTRUCTION	Round Pond, PR 432	Plum Point, NL	Regular Inspection	901499	4			Part XXII - Access and Egress	458 2-	- Access, egress and movement
2015/07/25	JOHNSON 'S CONSTRUCTION	Daniel's Harbour Camp	Daniel's Harbour, NL	Regular Inspection	901503	1	Occupational Health and Safety	26 - 2	-Powers of investigation		
2015/07/25	JOHNSON 'S CONSTRUCTION	Daniel's Harbour Camp	Daniel's Harbour, NL	Regular Inspection	901503	2			Part XXVI - Electrical Operations	481 1-a	- Space around equipment
2015/07/25	JOHNSON 'S CONSTRUCTION	Daniel's Harbour Camp	Daniel's Harbour, NL	Regular Inspection	901503	3			Part VI - Occupational Health Requirement	63 -a	- Emergency washing facility
2015/07/25	JOHNSON 'S CONSTRUCTION	Daniel's Harbour Camp	Daniel's Harbour, NL	Regular Inspection	901503	4			Part XXVI - Electrical Operations	478 1-	- Electrical requirements
2015/07/25	JOHNSON 'S CONSTRUCTION	Daniel's Harbour Camp	Daniel's Harbour, NL	Regular Inspection	901503	5			Part XXI - Welding, Burning & Cutting Op	450 2-	- Compressed gas cylinders
2017/03/29	JOHNSON 'S CONSTRUCTION	Site clean up	Lighthouse Road, Cape Ray, NL	Regular Inspection	931966	1			Part XII - Powered Mobile Equipment	267 1-	- Start of shift inspection
2016/11/08	JSM ELECTRICAL LTD	Switchyard Construction	Granite Canal Transmission Line Construction	Regular Inspection	661833	1			Part XX - Fire Prevention & Control	443 1-	- Fire protection
2017/03/08	JSM ELECTRICAL LTD	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941599	1			Part VI - Occupational Health Requirement	67 -d	- Sanitary and orderly conditions
2017/03/08	JSM ELECTRICAL LTD	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941599	2			Part XI - Scaffolds, Stages & Work Platform	161 1-	- Guardrails and toeboards
2017/04/11	JSM ELECTRICAL LTD	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941642	0					
2016/12/07	JSM ELECTRICAL LTD	Churchill Falls Project	Labrador	Regular Inspection	1040363	1			Part XX - Fire Prevention & Control	443 1-	- Fire protection
2016/12/07	JSM ELECTRICAL LTD	Churchill Falls Project	Labrador	Regular Inspection	1040363	2			Part XV - Rigging	366 -	- Storage
2016/12/07	JSM ELECTRICAL LTD	Churchill Falls Project	Labrador	Regular Inspection	1040363	3			Part VIII - Machinery and Equipment	88 1-b i	- Safe machinery and equipment
2016/12/07	JSM ELECTRICAL LTD	Churchill Falls Project	Labrador	Regular Inspection	1040363	4			OHS First Aid Regulations	17 -	- #2 First Aid Kit
2016/12/07	JSM ELECTRICAL LTD	Churchill Falls Project	Labrador	Regular Inspection	1040363	5			Part XX - Fire Prevention & Control	443 1-	- Fire protection
2013/09/18	LABRADOR CATERING LIMITED PARTNERSHIP	Temporary Camp	Muskat Falls, NL	Regular Inspection	671571	1			Part III - General Duties	14 1-	- General duties of employer
2013/09/18	LABRADOR CATERING LIMITED PARTNERSHIP	Temporary Camp	Muskat Falls, NL	Regular Inspection	671571	2			Part III - General Duties	12 2-g,ii	- Occupational health and safety
2013/09/18	LABRADOR CATERING LIMITED PARTNERSHIP	Temporary Camp	Muskat Falls, NL	Regular Inspection	671571	3	Occupational Health and Safety	5 - b	-Specific duties of employers		
2013/09/18	LABRADOR CATERING LIMITED PARTNERSHIP	Temporary Camp	Muskat Falls, NL	Regular Inspection	671571	4	Occupational Health and Safety	5.2 - b	-Specific duties of supervisor		
2016/08/09	LABRADOR CATERING LIMITED PARTNERSHIP	Bridge Repairs Caroline Brook West	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671955	1			Part XVI - Traffic Control	374 1-a	- Traffic control person
2016/08/09	LABRADOR CATERING LIMITED PARTNERSHIP	Bridge Repairs Caroline Brook West	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671955	2			Part XVI - Traffic Control	373 3-	- Traffic control
2013/06/18	LABRADOR CATERING LIMITED PARTNERSHIP	Temporary Camp	Muskat Falls, NL	Regular Inspection	720033	0					
2016/06/29	LABRADOR CATERING LIMITED PARTNERSHIP	Camp	Churchill Falls, NL	Regular Inspection	1070242	1			OHS First Aid Regulations	7 -b	- Notice to be posted
2016/06/29	LABRADOR CATERING LIMITED PARTNERSHIP	Camp	Churchill Falls, NL	Regular Inspection	1070242	2			Part XXVI - Electrical Operations	481 1-b	- Space around equipment
2016/06/29	LABRADOR CATERING LIMITED PARTNERSHIP	Camp	Churchill Falls, NL	Regular Inspection	1070242	3			Part III - General Duties	13 1-a	- Occupational health and safety
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	1			Part XII - Powered Mobile Equipment	269 -	- Unattended equipment
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	2			Part XXII - Access and Egress	458 4-	- Access, egress and movement
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	3			Part XXII - Access and Egress	458 1-	- Access, egress and movement
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	4			Part III - General Duties	14 1-	- General duties of employer
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	5			Part XX - Fire Prevention & Control	444 5-	- Fire and explosion
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	6			Part XXVI - Electrical Operations	478 1-	- Electrical requirements
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671722	7			Part IX - De-Energization and Lockout	128 -	- General requirement
2015/05/13	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671756	1			Part V - General Health & Safety Require	36 2-	- Illumination
2015/05/13	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671756	2			Part VI - Occupational Health Requirement	45 2-	- Ventilation
2015/05/13	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Regular Inspection	671756	3			Part XXXII - Open Cut Workings in Minin	655 1-e i	- Protective curbs or berms
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	1			Part VI - Occupational Health Requirement	68 1-b	- Noise hazards
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	2			Part VI - Occupational Health Requirement	68 5-	- Noise hazards
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	3			Part VI - Occupational Health Requirement	68 3-b	- Noise hazards
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	4			Part VI - Occupational Health Requirement	68 2-	- Noise hazards
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	5	Occupational Health and Safety	26 - 1b	-Powers of investigation		
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	6			Part VII - Personal Protective Equipment	86 1-	- Inspection and maintenance
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	7			Part V - General Health & Safety Require	36 5-	- Illumination
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	8			Part VI - Occupational Health Requirement	45 1-c	- Ventilation
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	9			Part XXVI - Electrical Operations	478 1-	- Electrical requirements
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	10			Part VI - Occupational Health Requirement	45 1-a	- Ventilation
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	11			Part VII - Personal Protective Equipment	84 1-	- Respiratory protection
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	12			Part VI - Occupational Health Requirement	67 -a	- Sanitary and orderly conditions
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	13			Part VI - Occupational Health Requirement	45 2-	- Ventilation
2014/04/10	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860235	14			Part VI - Occupational Health Requirement	42 7-c	- Hazardous substances
2014/07/08	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860256	0					
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	1			Part V - General Health & Safety Require	28 3-	- Guardrails
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	2	Occupational Health and Safety	26 - 1b	-Powers of investigation		
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	3			Part VIII - Machinery and Equipment	97 -b	- Restraining devices
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	4			Part VI - Occupational Health Requirement	42 11-	- Hazardous substances
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	5			Part XXXII - Open Cut Workings in Minin	655 1-e i	- Protective curbs or berms
2014/10/16	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860288	6			Part XXVI - Electrical Operations	481 1-b	- Space around equipment
2015/01/28	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860316	0					
2015/04/14	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860339	1			Part VI - Occupational Health Requirement	63 -a	- Emergency washing facility
2015/06/17	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860359	1			Part VI - Occupational Health Requirement	45 3-	- Ventilation
2015/06/17	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860359	2			Part VI - Occupational Health Requirement	42 4-	- Hazardous substances
2015/06/17	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860359	3			Part VI - Occupational Health Requirement	45 9-b	- Ventilation
2015/06/17	LABRADOR READY-MIX LTD.	Lower Churchill Project	Muskat Falls, NL	Hygiene Assessment	860359	4	Occupational Health and Safety	26 - 1b	-Powers of investigation		
2014/01/14	LANCASTER SHEET METAL LIMITED	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	940648	2	Occupational Health and Safety	27 - 1a	-Stop work orders		
2014/01/14	LANCASTER SHEET METAL LIMITED	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	940648	2			Part XI - Scaffolds, Stages & Work Platform	207 1-	- Fall protection-elevating
2016/11/00	LANCOR CONCRETE CONTRACTORS LTD.	Form work	Cape Ray Transition Site, Cape Ray, NL	Regular Inspection	941534	1			Part XXV - Electrical Operations	478 1-	- Electrical requirements
2016/11/00	LANCOR CONCRETE CONTRACTORS LTD.	Form work	Cape Ray Transition Site, Cape Ray, NL	Regular Inspection	941534	1			Part XV - Rigging	365 -	- Inspection before use
2016/11/00	LANCOR CONCRETE CONTRACTORS LTD.	Form work	Cape Ray Transition Site, Cape Ray, NL	Regular Inspection	941534	2			Part VI - Occupational Health Requirement	62 1-a	- Washing facilities
2016/12/15	LANCOR CONCRETE CONTRACTORS LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941573	1			Part V - General Health & Safety Require	28 1-	- Guardrails
2016/12/15	LANCOR CONCRETE CONTRACTORS LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941573	2			Part XXII - Access and Egress	458 1-	- Access, egress and movement
2016/11/03	LEG	Section 4; Structure 12; Long Range	Taylor's Brook Rd., Jackson's Arm, NL	Regular Inspection	901852	1	Occupational Health and Safety	27 - 1b	-Stop work orders		
2016/11/03	LEG	Section 4; Structure 12; Long Range	Taylor's Brook Rd., Jackson's Arm, NL	Regular Inspection	901852	2			Part XXII - Access and Egress	458 1-	- Access, egress and movement
2016/11/03	LEG	Section 4; Structure 12; Long Range	Taylor's Brook Rd., Jackson's Arm, NL	Regular Inspection	901852	3			Part XVII - Excavation, Underground Work	413 6-	- Air quality
2016/11/03	LEG	Section 4; Structure 12; Long Range	Taylor's Brook Rd., Jackson's Arm, NL	Regular Inspection	901852	4			Part VII - Personal Protective Equipment	83 -	- Respiratory protection pro
2016/11/03	LEG	Section 4; Structure 12; Long Range	Taylor's Brook Rd., Jackson's Arm, NL	Regular Inspection	901852	5			Part VII - Personal Protective Equipment	85 5-a	- Respiratory protection equip
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	1			Part VII - Personal Protective Equipment	85 5-a	- Respiratory protection equip
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	2			Part III - General Duties	12 1-g i	- Occupational health and safety
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	1			Part XX - Fire Prevention & Control	443 2-	- Fire protection
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	2			Part V - General Health & Safety Require	36 1-	- Illumination

2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	3			Part VII - Personal Protective Equipment	85	5-a	- Respiratory protection equip	
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	4			Part VII - Personal Protective Equipment	81	-	- High visibility apparel	
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	5			Part XII - Powered Mobile Equipment	267	1-	- Start of shift inspection	
2017/06/15	LEG	Drilling operation	Structure 410, Battle Barrens Road, Long Range Mountains, NL	Regular Inspection	932058	6			Part XV - Rigging	365	-	- Inspection before use	
2015/10/20	LES EXCAVATIONS MARCHAND ET FILS	Switchyard	Churchill Falls, NL	Regular Inspection	860397	1			Part VIII - Machinery and Equipment	100	1-	- Conveyor standards	
2015/10/20	LES EXCAVATIONS MARCHAND ET FILS	Switchyard	Churchill Falls, NL	Regular Inspection	860397	2			Part V - General Health & Safety Require	36	2-	- Illumination	
2015/10/20	LES EXCAVATIONS MARCHAND ET FILS	Switchyard	Churchill Falls, NL	Regular Inspection	860397	3			Part IX - De-Energization and Lockout	128	-	- General requirement	
2016/08/11	LES STRUCTURES DE BEAUCE INC.	Control Rm. of GIS Bldg.	LCP, Churchill Falls Switchyard, NL	Regular Inspection	671958	1			Part X - Fall Protection	142	1-b i	- Fall arrest system	
2016/08/11	LES STRUCTURES DE BEAUCE INC.	Control Rm. of GIS Bldg.	LCP, Churchill Falls Switchyard, NL	Regular Inspection	671958	2			Part X - Fall Protection	141	-b & d -h	- General requirements	
2016/08/11	LES STRUCTURES DE BEAUCE INC.	Control Rm. of GIS Bldg.	LCP, Churchill Falls Switchyard, NL	Regular Inspection	671958	3			Part XXII - Access and Egress	460	1-a	- Stairs	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	1	Occupational Health and Safety	27 - 1a	- Stop work orders	Part XXVIII - Excavation, Underground Work	414	-a	- Rock crushing control meas
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	2	Occupational Health and Safety	27 - 1a	- Stop work orders	Part XXVIII - Excavation, Underground Work	414	-a	- Rock crushing control meas
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	3			Part VI - Occupational Health Requirement	43	5-	- Health surveillance	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	4			Part VI - Occupational Health Requirement	45	2-	- Ventilation	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	5			Part VI - Occupational Health Requirement	68	5-	- Noise hazards	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	6			Part XXXII - Open Cut Workings in Minin	655	1-e i	- Protective curbs or berms	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	7			Part XXVI - Electrical Operations	481	2-	- Space around equipment	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	8			Part XXVI - Electrical Operations	478	1-	- Electrical requirements	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	9			Part XV - Rigging	365	-	- Inspection before use	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	10			Part VII - Personal Protective Equipment	74	2-	- General requirements of safety	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	11			Part VI - Occupational Health Requirement	42	1-	- Hazardous substances	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	12			Part VI - Occupational Health Requirement	42	11-	- Hazardous substances	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	13			Part VII - Personal Protective Equipment	83	-	- Respiratory protection pro	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	14			Part XXXII - Open Cut Workings in Minin	656	2-	- Heights of faces and bench	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	15			Part XIX - General Blasting	439	3-	- Post-firing	
2012/09/25	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500893	16	Occupational Health and Safety	10-	- Duty of principal contractor				
2012/11/27	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Investigate Accident	500924	1	Occupational Health and Safety	54 - 1b	- Reporting accidents				
2013/03/27	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500954	0							
2013/01/16	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671519	1	Occupational Health and Safety	27 - 1a	- Stop work orders	Part VI - Occupational Health Requirement	42	1-	- Hazardous substances
2013/01/16	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671519	2			Part XXVI - Electrical Operations	488	2-	- Grounding portable low vol	
2013/01/16	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671510	3			Part VIII - Machinery and Equipment	88	1-a	- Safe machinery and equipment	
2013/01/16	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671510	4			Part XV - Rigging	353	1-	- Open hook restriction	
2013/03/26	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671535	1			Part XIX - General Blasting	417	0-	- Definitions	
2013/03/26	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671535	2			Part XIX - General Blasting	419	1-	- Role of certified blaster	
2013/03/26	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671535	3			Part XII - Powered Mobile Equipment	251	1-	- Operation and maintenance	
2013/09/17	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671569	1			Part XVI - Traffic Control	373	3-	- Traffic control	
2013/09/17	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671569	2			Part XII - Powered Mobile Equipment	255	1-b	- Warning signal device	
2013/09/17	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671569	3			Part XVIII - Excavation, Underground Work	410	1-	- Excavation safety	
2013/09/17	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671569	4			Part XVII - Construction, Excavation & D	403	-	- Stairways	
2013/11/26	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	671608	1	Occupational Health and Safety	10-	- Duty of principal contractor				
2014/10/16	LIANNU, A LIMITED PARTNERSHIP	Bridge Construction	Mackenzie River, Muskrat Falls, NL	Regular Inspection	671698	1			Part XXII - Access and Egress	458	1-	- Access, egress and movement	
2014/11/25	LIANNU, A LIMITED PARTNERSHIP	Bridge Construction	Mackenzie River, Muskrat Falls, NL	Regular Inspection	671710	1			Part V - General Health & Safety Require	28	1-	- Guardrails	
2014/01/14	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	940647	1			Part V - General Health & Safety Require	28	1-	- Guardrails	
2014/01/14	LIANNU, A LIMITED PARTNERSHIP	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	940647	2			Part V - General Health & Safety Require	36	1-	- Illumination	
2016/04/15	LOCKES ELECTRICAL LIMITED	Transmission Line Installation	Soliders Pond, TCH North, NL	Regular Inspection	671906	1	Occupational Health and Safety	27 - 1a	- Stop work orders	Part VI - Occupational Health Requirement	46	3-c	- Silica regulation
2017/02/08	LOCKES ELECTRICAL LIMITED	North Side of AC Control Bldg.	Soliders Pond Switchyard, NL	Investigate Accident	672017	0							
2014/10/21	LOCKES ELECTRICAL LIMITED	Soliders Pond	Off the Trans Canada Highway, NL	Regular Inspection	1010072	1			Part V - General Health & Safety Require	38	2-	- Emergency plan risk assess	
2014/10/21	LOCKES ELECTRICAL LIMITED	Soliders Pond	Off the Trans Canada Highway, NL	Regular Inspection	1010072	2			OHS First Aid Regulations	7	-b	- Notice to be posted	
2016/04/18	LOGAN DRILLING LTD	Transmission line work	Maritime Link Project, West of the Burgeo TCH intersection	Investigate Incident	931572	1	Occupational Health and Safety	26 - 2	- Powers of investigation				
2016/04/18	LOGAN DRILLING LTD	Transmission line work	Maritime Link Project, West of the Burgeo TCH intersection	Investigate Incident	931572	2	Occupational Health and Safety	54 - 1b	- Reporting accidents				
2017/04/05	LOGAN DRILLING LTD	Drill testing support for new tower	Access AT319, Structure SD040	Regular Inspection	931978	1			Part XV - Rigging	365	-	- Inspection before use	
2017/04/05	LOGAN DRILLING LTD	Drill testing support for new tower	Access AT319, Structure SD040	Regular Inspection	931978	2	Smoke-free Environment Act, 2005	4 - 1a	- Prohibition				
2017/04/05	LOGAN DRILLING LTD	Drill testing support for new tower	Access AT319, Structure SD040	Regular Inspection	931978	3			Part VI - Occupational Health Requirement	61	1-	- Toilet facilities	
2017/04/05	LOGAN DRILLING LTD	Drill testing support for new tower	Access AT319, Structure SD040	Regular Inspection	931978	4			Part VI - Occupational Health Requirement	62	1-a	- Washing facilities	
2017/04/05	LOGAN DRILLING LTD	Drill testing support for new tower	Access AT319, Structure SD040	Regular Inspection	931978	5	Occupational Health and Safety	37 -	- Committees				
2017/06/06	LOGAN DRILLING LTD	Off loading drill rig	Access AT 229, near Structure SC091	Regular Inspection	932037	1			Part VI - Occupational Health Requirement	61	1-	- Toilet facilities	
2017/06/06	LOGAN DRILLING LTD	Off loading drill rig	Access AT 229, near Structure SC091	Regular Inspection	932037	2			Part VI - Occupational Health Requirement	62	1-a	- Washing facilities	
2012/09/13	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	600800	1			Part VI - Occupational Health Requirement	67	-d	- Sanitary and orderly conditions	
2012/09/13	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	600800	2			Part V - General Health & Safety Require	28	6-	- Guardrails	
2012/09/13	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	600800	3			Part XXVI - Electrical Operations	489	1-	- Low voltage-ground fault i	
2012/09/13	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	600800	4			Part VII - Personal Protective Equipment	75	-	- Eye and face protection	
2014/02/19	MAJORS LOGGING LIMITED	Truck Repairs, Granite Canal Road	South of Millertown	Regular Inspection	661396	1			Part VII - Personal Protective Equipment	75	-	- Eye and face protection	
2014/02/19	MAJORS LOGGING LIMITED	Truck Repairs, Granite Canal Road	South of Millertown	Regular Inspection	661396	2			Part XXVI - Electrical Operations	478	1-	- Electrical requirements	
2014/02/19	MAJORS LOGGING LIMITED	Truck Repairs, Granite Canal Road	South of Millertown	Regular Inspection	661396	3			OHS First Aid Regulations	4	4-	- Duties of employer	
2014/02/19	MAJORS LOGGING LIMITED	Truck Repairs, Granite Canal Road	South of Millertown	Regular Inspection	661396	4			Part X - Fall Protection	141	-a & d -h	- General requirements	
2014/02/19	MAJORS LOGGING LIMITED	Truck Repairs, Granite Canal Road	South of Millertown	Regular Inspection	661396	5			Part XXVI - Electrical Operations	489	1-	- Low voltage-ground fault i	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	1			Part XII - Powered Mobile Equipment	255	1-b	- Warning signal device	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	2			Part XII - Powered Mobile Equipment	255	1-b	- Warning signal device	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	3			Part XX - Fire Prevention & Control	443	1-	- Fire protection	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	4			Part VIII - Machinery and Equipment	88	1-a	- Safe machinery and equipment	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	5			Part XI - Scaffolds, Stages & Work Platform	148	1-a	- Portable ladder standards	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	6			Part XXI - Welding, Burning & Cutting Op	449	4-	- Gas welding and burning	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	7			Part XXI - Welding, Burning & Cutting Op	450	1-a i	- Compressed gas cylinders	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	8			Part XV - Rigging	353	1-	- Open hook restriction	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	9			Part XV - Rigging	365	-	- Inspection before use	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	10			Part XXVI - Electrical Operations	478	1-	- Electrical requirements	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	11			Part VI - Occupational Health Requirement	63	-a	- Emergency washing facility	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	12			Part VIII - Machinery and Equipment	88	1-a	- Safe machinery and equipment	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	13			Part XII - Powered Mobile Equipment	251	3-	- Operation and maintenance	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	14			Part XII - Powered Mobile Equipment	257	1-	- Start of shift inspection	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	15			Part XII - Powered Mobile Equipment	255	1-b	- Warning signal device	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	16			Part XII - Powered Mobile Equipment	253	6-	- Operation and maintenance	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	17			Part XII - Powered Mobile Equipment	257	1-	- Rear view mirror	
2013/05/16	MAJORS LOGGING LIMITED	112 TCH	Deer Lake, NL	Regular Inspection	900902	18			Part XII - Powered Mobile Equipment	266	1-	- Seating and standard requirement	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	1	Occupational Health and Safety	27 - 1b	- Stop work orders	Part XXVIII - Excavation, Underground Work	406	4-a	- Pre-excavation requirement

2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	2			Part XVIII - Excavation, Underground Work	408 1-a	- Removal of material	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	3			Part XVIII - Excavation, Underground Work	407 1-	-Excavation or access	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	4	Occupational Health and Safety	5 - b	-Specific duties of employers			
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	5			Part XII - Powered Mobile Equipment	267 1-	-Start of shift inspection	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	6			Part XX - Fire Prevention & Control	443 1-	- Fire protection	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	7			Part III - General Duties	18 1-	- Safety inspections	
2016/12/01	MAJORS LOGGING LIMITED	Access 120	Off of the Burgeo Highway, NL	Regular Inspection	931863	8	Smoke-free Environment Act, 2005	4 - 1a	-Prohibition			
2015/09/16	MAJORS LOGGING LIMITED	Maritime Link, logging operation	~ 3km off the Burgeo hwy, ~ 5km fr Burgeo hwy turnoff	Investigate incident	941179	1	Occupational Health and Safety	27 - 1b	-Stop work orders	Part III - General Duties	16 2-c	- Safe working load of equip
2015/09/16	MAJORS LOGGING LIMITED	Maritime Link, logging operation	~ 3km off the Burgeo hwy, ~ 5km fr Burgeo hwy turnoff	Investigate incident	941179	2	Occupational Health and Safety	26 - 2	-Powers of investigation			
2016/12/01	MAJORS LOGGING LIMITED	Traffic Control	Access road 216, TCH	Regular Inspection	941549	0						
2016/12/01	MAJORS LOGGING LIMITED	Laying mats	Access road 315, TCH	Regular Inspection	941554	1			OHS First Aid Regulations	4 3-	-Duties of employer	
2016/12/01	MAJORS LOGGING LIMITED	Laying mats	Access road 315, TCH	Regular Inspection	941554	2			Part XII - Powered Mobile Equipment	267 1-	-Start of shift inspection	
2017/03/08	MAJORS LOGGING LIMITED	Outside HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941607	1			OHS First Aid Regulations	4 3-	-Duties of employer	
2017/03/08	MAJORS LOGGING LIMITED	Outside HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941607	2			Workplace Hazardous Materials Information	9 1-	-Decanted Products	
2014/05/22	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	1020025	1	Occupational Health and Safety	5.1 -	-Supervisors' general duty			
2014/05/22	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	1020025	2			OHS First Aid Regulations	4 3-	-Duties of employer	
2014/05/22	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	1020025	3			Part XXVI - Electrical Operations	483 -	-Powerline hazards training	
2014/05/22	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	1020025	4			Part VI - Occupational Health Requirement	63 -a	-Emergency washing facility	
2014/05/22	MAJORS LOGGING LIMITED	Camp 153, White Wash Road	Bonne Bay Pond Area	Regular Inspection	1020025	5			Part VII - Powered Mobile Equipment	251 6-	-Operation and maintenance	
2015/07/16	MARINE CONTRACTORS INC	Cape Ray Pit & Cape Ray Hydro Line	Cape Ray, NL	Regular Inspection	901490	1			Part XVIII - Excavation, Underground Work	414 -a	-Rock crushing control meas	
2015/07/22	MARINE CONTRACTORS INC	Maritime Link Project - Access Road	Cape Ray, NL	Regular Inspection	931263	1			Part XII - Powered Mobile Equipment	267 1-	-Start of shift inspection	
2015/07/22	MARINE CONTRACTORS INC	Maritime Link Project - Access Road	Cape Ray, NL	Regular Inspection	931263	2			Part XXXII - Open Cut Workings in Minin	666 1-a & b	- Light vehicle equipment	
2015/08/25	MARINE CONTRACTORS INC	Maritime Link Project - Access Road	Cape Ray, NL	Regular Inspection	931263	3			Part XXXII - Open Cut Workings in Minin	666 1-a & b	- Light vehicle equipment	
2015/08/27	MARINE CONTRACTORS INC	Accident investigations	Granite Canal & Bottom Brook, NL	Investigate Incident	941164	1	Occupational Health and Safety	26 - 2	-Powers of investigation			
2015/08/27	MARINE CONTRACTORS INC	Accident investigations	Granite Canal & Bottom Brook, NL	Investigate Incident	941164	2	Occupational Health and Safety	26 - 2	-Powers of investigation			
2015/08/27	MARINE CONTRACTORS INC	Accident investigations	Granite Canal & Bottom Brook, NL	Investigate Incident	941164	2	Occupational Health and Safety	54 - 1b	-Reporting accidents			
2016/01/20	MARINE CONTRACTORS INC	Maritime Link Project	Cape Ray, NL	Regular Inspection	941298	1			Part XVIII - Excavation, Underground Work	414 -a	- Rock crushing control meas	
2016/01/20	MARINE CONTRACTORS INC	Maritime Link Project	Cape Ray, NL	Regular Inspection	941298	2			Part VI - Occupational Health Requirement	42 7-a	- Hazardous substances	
2016/04/18	MARINE CONTRACTORS INC	Maritime Link Project	Bottom Brook, NL	Investigate Accident	941352	1	Occupational Health and Safety	27 - 1b	-Stop work orders	Part III - General Duties	14 1-	-General duties of employer
2016/04/18	MARINE CONTRACTORS INC	Maritime Link Project	Bottom Brook, NL	Investigate Accident	941352	2	Occupational Health and Safety	26 - 2	-Powers of investigation			
2017/03/08	MASTEC CANADA CONSTRUCTION INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941614	0						
2017/04/11	MASTEC CANADA CONSTRUCTION INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941643	0						
2017/04/11	MCCARTHY'S ROOFING LTD	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931988	1						
2014/04/10	MIKE KELLY & SONS LTD	Temporary Bridge Installation	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671649	0			Part VII - Personal Protective Equipment	74 2-	-General requirements of safety	
2016/11/03	MIKE KELLY & SONS LTD	NALCOR Site, Taylor's Brook Road	Jackson's Arm, NL	Regular Inspection	901854	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/06/30	MJR MASONRY	Condenser Bldg	Soldiers Pond, NL	Regular Inspection	671938	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part VI - Occupational Health Requirement	46 3-c	-Silica regulation
2016/06/30	MJR MASONRY	Condenser Bldg	Soldiers Pond, NL	Regular Inspection	671938	2			Part XI - Scaffolds, Stages & Work Platform	161 1-	-Guardrails and toeboards	
2016/06/30	MJR MASONRY	Condenser Bldg	Soldiers Pond, NL	Regular Inspection	671938	3			Part XI - Scaffolds, Stages & Work Platform	161 2-	-Guardrails and toeboards	
2017/03/08	MSM CONSTRUCTION SERVICES LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941601	1			Part XII - Powered Mobile Equipment	275 1-	-Securing loads	
2017/03/08	MSM CONSTRUCTION SERVICES LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941601	2			Part VII - Personal Protective Equipment	71 -a	-Selection, use and maintain	
2017/04/11	MSM CONSTRUCTION SERVICES LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941640	1			Part VII - Personal Protective Equipment	74 2-	-General requirements of safety	
2012/09/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	500895	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/01/15	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	500935	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/03/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	500952	1			Part XX - Fire Prevention & Control	443 1-	-Fire protection	
2013/03/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	500952	2	Occupational Health and Safety	26.2 -	-Requirement to provide assist			
2013/03/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	500952	3	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/06/13	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	501008	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/09/17	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	501036	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/11/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	501065	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/11/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	501070	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2014/03/31	NALCOR ENERGY	Nalcor Energy Worksite	Shoal Cove East - Route 430	Regular Inspection	501104	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2015/03/18	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Goose Bay, NL	Regular Inspection	501223	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2013/04/24	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671540	0						
2013/09/18	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Investigate Complaint	671570	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2014/01/14	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671630	0						
2014/01/15	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671633	0						
2014/01/24	NALCOR ENERGY	Chlorination Bldg	Main Camp, Lower Churchill Project, NL.	Regular Inspection	671636	1			Part VI - Occupational Health Requirement	45 4 -	- Ventilation	
2014/01/24	NALCOR ENERGY	Chlorination Bldg	Main Camp, Lower Churchill Project, NL.	Regular Inspection	671636	2			Part VI - Occupational Health Requirement	59 2-d	-Storage of hazardous substance	
2014/01/24	NALCOR ENERGY	Chlorination Bldg	Main Camp, Lower Churchill Project, NL.	Regular Inspection	671636	3			Part VI - Occupational Health Requirement	63 -a	-Emergency washing facility	
2014/01/24	NALCOR ENERGY	Chlorination Bldg	Main Camp, Lower Churchill Project, NL.	Regular Inspection	671636	4			Part III - General Duties	14 1-	-General duties of employer	
2014/01/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671637	1			Part III - General Duties	12 1-i	-Occupational health and safety	
2014/01/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671637	2			Part III - General Duties	12 1-g ii	-Occupational health and safety	
2014/01/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671637	3			Part III - General Duties	12 1-i	-Occupational health and safety	
2014/03/04	NALCOR ENERGY	Marshalling Yard	Lower Churchill Project, Happy Valley-Goose Bay, NL.	Regular Inspection	671642	0						
2014/04/10	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671650	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2014/04/10	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671650	2			Part III - General Duties	12 1-i	- Occupational health and safety	
2014/04/30	NALCOR ENERGY	Site Development	Soldiers Pond, TCH, NL.	Regular Inspection	671652	0						
2014/06/02	NALCOR ENERGY	Site Development	Soldiers Pond, TCH, NL.	Regular Inspection	671661	0						
2014/06/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Investigate Incident	671663	1			Part III - General Duties	12 1-g iv	-Occupational health and safety	
2014/06/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Investigate Accident	671664	1			Part III - General Duties	12 1-g iv	-Occupational health and safety	
2014/07/02	NALCOR ENERGY	Site Development	Soldiers Pond, TCH, NL.	Regular Inspection	671666	0						
2014/07/03	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671668	0						
2014/07/08	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671671	0						
2014/07/10	NALCOR ENERGY	Switchyard Development	Lower Churchill Project, Churchill Falls, NL.	Regular Inspection	671673	0						
2014/08/12	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671681	0						
2014/08/13	NALCOR ENERGY	Reservoir Clearing	Lower Churchill Project, Muskrat Falls, NL.	Regular Inspection	671683	0						
2014/11/25	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671711	0						
2015/01/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671723	1			Part XXII - Access and Egress	458 1-	- Access, egress and movement	
2015/01/27	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671723	2			Part XX - Fire Prevention & Control	443 2-	-Fire protection	
2015/01/29	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671725	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2015/02/23	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671731	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2015/04/16	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671739	1			Part III - General Duties	12 1-i	-Occupational health and safety	
2015/04/16	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671739	2			Part III - General Duties	18 2-	- Safety inspections	
2015/04/24	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671743	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2015/04/29	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671746	0						

2015/05/13	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671757	0						
2015/08/04	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671795	0						
2015/08/06	NALCOR ENERGY	Site Development	Dowden's Point Seal Cove, NL	Regular Inspection	671798	1	Occupational Health and Safety	5 - d	-Specific duties of employers			
2015/10/21	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671838	0						
2015/10/22	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671839	0						
2015/12/03	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671866	0						
2016/02/23	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Happy Valley -Goose Bay, NL	Regular Inspection	671892	0						
2016/03/08	NALCOR ENERGY	Geotechnical Drilling Operation	Structure 501, St. Paul River Rd., NL	Regular Inspection	671896	1	Occupational Health and Safety	26 - 2	-Powers of investigation			
2016/03/17	NALCOR ENERGY	LCP Office	Torbay Rd, St. John's, NL	Regular Inspection	671897	0						
2016/04/15	NALCOR ENERGY	Transmission Line Installation	Soliders Pond TCH North, NL	Regular Inspection	671907	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/05/30	NALCOR ENERGY	Draft Tube Number 2	Muskrat Falls Powerhouse, Happy Valley-Goose Bay, NL	Regular Inspection	671925	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/05/30	NALCOR ENERGY	Draft Tube Number 2	Muskrat Falls Powerhouse, Happy Valley-Goose Bay, NL	Regular Inspection	671925	2	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/07/20	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671946	0						
2016/09/13	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	671971	0						
2016/10/20	NALCOR ENERGY	Transmission Tower Installation	Western NL	Regular Inspection	671993	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/10/20	NALCOR ENERGY	Transmission Tower Installation	Western NL	Regular Inspection	671993	2				Part III - General Duties	12 1-a	- Occupational health and safety
2016/11/09	NALCOR ENERGY	Foundation Work	Structure 81, LCP Transmission Line	Regular Inspection	672004	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/12/06	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	672008	0						
2017/04/26	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	672045	0						
2017/03/08	NALCOR ENERGY	Transmission Tower Installation	Witless Bay Line, NL	Regular Inspection	720089	0						
2014/03/04	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860227	1				Workplace Hazardous Materials Information	13 1-	- Supplier Material Safety D
2014/03/04	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860227	2				Part VI - Occupational Health Requirement	42 1-	- Hazardous substances
2014/03/04	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860227	3				Part III - General Duties	12 1-e	- Occupational health and safety
2014/03/04	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860227	4	Occupational Health and Safety	26 - 1b	-Powers of investigation			
2014/07/08	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860258	1				Part VI - Occupational Health Requirement	46 3-d	- Silica regulation
2014/08/25	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Hygiene Assessment	860267	0						
2014/10/15	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860285	0						
2014/10/16	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860287	1				Workplace Hazardous Materials Information	9 1-	- Decanted Products
2014/10/16	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860287	2				Part VI - Occupational Health Requirement	42 11-	- Hazardous substances
2014/10/16	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860287	3				Part VI - Occupational Health Requirement	63 -c	- Emergency washing facility
2015/01/28	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860318	1				Part VI - Occupational Health Requirement	61 1-	- Toilet facilities
2015/01/28	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860318	2				Part VI - Occupational Health Requirement	45 5-a	- Ventilation
2015/01/28	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860318	3				Workplace Hazardous Materials Information	9 1-	- Decanted Products
2015/04/14	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860340	0						
2015/06/16	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Hygiene Assessment	860360	0						
2015/10/21	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	860398	1				Part VI - Occupational Health Requirement	67 -c	- Sanitary and orderly conditions
2015/10/21	NALCOR ENERGY	Lower Churchill Project	Happy Valley-Goose Bay, NL	Regular Inspection	860398	2				Part III - General Duties	18 1-	- Safety inspections
2017/06/15	NALCOR ENERGY	Transmission line project	Long Range Mountains, NL	Regular Inspection	932059	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2017/06/15	NALCOR ENERGY	Transmission line project	Long Range Mountains, NL	Regular Inspection	932059	2				Part XXXII - Open Cut Workings in Minin	655 1-f	- Protective curbs or berms
2016/10/27	NALCOR ENERGY	Transmission Line Project	Dawes Pond & Catamaran Project Locations	Regular Inspection	951035	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2016/10/27	NALCOR ENERGY	Transmission Line Project	Dawes Pond & Catamaran Project Locations	Regular Inspection	951035	2				Part III - General Duties	21 -a	- Appointment of qualified c
2017/06/16	NALCOR ENERGY	Transmission Line Project	Access from Buchans Highway & Sandy Resource Road GFW	Regular Inspection	951179	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2014/08/01	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010059	0						
2014/08/25	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Investigate Incident	1010062	0						
2014/09/09	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Follow-up	1010065	0						
2014/10/02	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010071	0						
2014/10/21	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010073	1	Occupational Health and Safety	10 -	-Duty of principal contractor			
2014/11/27	NALCOR ENERGY	Transmission Tower Installation	Lower Churchill Project, Goose Bay, NL	Regular Inspection	1010076	0						
2015/05/28	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010082	0						
2015/08/14	NALCOR ENERGY	Site Development	Soliders Pond, TCH, NL	Regular Inspection	1010091	0						
2015/09/28	NALCOR ENERGY	Site Development	Dowden's Point, Seal Cove, NL	Regular Inspection	1010100	0						
2015/10/13	NEXANS NORWAY AS	Shoal Cove, NL	Shoal Cove, NL	Regular Inspection	901574	0						
2017/03/29	NEXANS NORWAY AS	Site clean up	Lighthouse Road, Cape Ray, NL	Regular Inspection	931968	0						
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part X - Fall Protection	141 -b & d	- General requirements
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	2				Part VII - Personal Protective Equipment	83 -	- Respiratory protection pro
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	3				Part VII - Personal Protective Equipment	71 -a	- Selection, use and maintain
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	4				Part VI - Occupational Health Requirement	42 7-a	- Hazardous substances
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	5				Part VI - Occupational Health Requirement	65 -	- Eating area
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	6				Part XIX - General Blasting	429 4-	- Drilling
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	7				Part XIX - General Blasting	439 3-	- Post-firing
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	8				Part XIX - General Blasting	434 3-	- Restrictions
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	9	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XIX - General Blasting	425 5-b	- Day box or magazine
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	10				Part VIII - Machinery and Equipment	88 2-a	- Safe machinery and equipment
2012/09/25	NFLD HARD ROK INC	Lower Churchill Development	Happy Valley-Goose Bay, NL	Regular Inspection	500894	11				Part XXXII - Open Cut Workings in Minin	656 2-	- Heights of faces and bench
2015/08/25	NFLD HARD ROK INC	Blasting	Cape Ray, NL	Investigate Incident	941159	1	Occupational Health and Safety	26 - 2	-Powers of investigation			
2015/08/25	NFLD HARD ROK INC	Blasting	Cape Ray, NL	Investigate Incident	941159	2				Part XIX - General Blasting	420 4-	- Security and report requirement
2015/08/28	NFLD HARD ROK INC	Blasting	Cape Ray, NL	Investigate Accident	941166	1	Occupational Health and Safety	26 - 2	-Powers of investigation			
2015/08/05	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671797	1				Part XII - Powered Mobile Equipment	251 5-	- Operation and maintenance
2015/08/05	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671797	2				Part VIII - Machinery and Equipment	88 1-b i	- Safe machinery and equipment
2016/09/26	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Forteau, NL	Investigate Accident	671974	1				Part III - General Duties	12 1-g iv	- Occupational health and safety
2016/10/14	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Forteau, NL	Follow-up	671982	0						
2015/10/22	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	860400	1				Part VI - Occupational Health Requirement	42 4-	- Hazardous substances
2015/10/22	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	DC Transmission Line	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	860400	2				Part VI - Occupational Health Requirement	45 8-	- Ventilation
2017/06/15	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	Drilling	Structure 575, Eagle Mountain Road, Long Range Mountains, NL	Regular Inspection	941681	1				Part VII - Personal Protective Equipment	71 -d	- Selection, use and maintain
2017/06/15	NORTHSTAR SHARP'S FOUNDATION SPECIALISTS LTD.	Drilling	Structure 575, Eagle Mountain Road, Long Range Mountains, NL	Regular Inspection	941681	2				Part VII - Personal Protective Equipment	251 1-	- Operation and maintenance
2014/01/15	NORTRAX	Johnsons Construction Camp 65	65km West Happy Valley-Goose Bay, Labrador	Regular Inspection	940650	1				Part VI - Occupational Health Requirement	63 -a	- Emergency washing facility
2014/01/15	NORTRAX	Johnsons Construction Camp 65	65km West Happy Valley-Goose Bay, Labrador	Regular Inspection	940650	2				OHS First Aid Regulations	4 3-	- Duties of employer
2016/12/15	PACER NEWFOUNDLAND AND LABRADOR CORPORAT	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941574	1				Part VI - Occupational Health Requirement	67 -d	- Sanitary and orderly conditions
2016/10/17	PENNECON HEAVY CIVIL LTD.	Emera Maritime Project	Entrance to Cape Ray - Route 408	Regular Inspection	501490	1	Occupational Health and Safety	37 -	-Committees			
2017/01/31	PENNECON HEAVY CIVIL LTD.	Switchyard Development	Soliders Pond, NL	Regular Inspection	672012	1				Part XII - Powered Mobile Equipment	253 2-	- Operator's responsibility
2017/01/31	PENNECON HEAVY CIVIL LTD.	Switchyard Development	Soliders Pond, NL	Regular Inspection	672012	2				Part III - General Duties	12 1-g i	- Occupational health and safety
2017/03/29	PENNECON HEAVY CIVIL LTD.	Excavation type work	Access 334, Tower SE 17, Cape Ray, NL	Regular Inspection	931970	0						
2016/08/10	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	671956	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part VI - Occupational Health Requirement	42 1-	- Hazardous substances
2016/08/11	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	671960	1				Part XVIII - Excavation, Underground Work	410 1-	- Excavation safety
2016/08/11	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	671960	2				Part XVII - Construction, Excavation & D	378 1-a	- Protection from falling ma

2015/10/20	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	1010103	1			Part XVII - Construction, Excavation & D	384 1-	-Concrete placing hazards	
2015/10/20	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	1010103	2			Part XVIII - Excavation, Underground Work	410 1-	-Excavation safety	
2015/10/20	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	1010103	3			Part VI - Occupational Health Requirement	42 7-a	-Hazardous substances	
2015/10/20	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	1010103	4			Part VIII - Machinery and Equipment	88 1-b i	-Safe machinery and equipment	
2015/10/20	POMERLEAU INC.	Churchill Falls Switchyard	Churchill Falls, Labrador	Regular Inspection	1010103	5			Part VI - Occupational Health Requirement	59 2-a	-Storage of hazardous substance	
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part V - General Health & Safety Require	28 1 -	-Guardrails
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	2	Occupational Health and Safety	29 - b	-Order re: equipment	Part III - General Duties	14 1 -	-General duties of employer
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	3			Part V - General Health & Safety Require	28 1 -	-Guardrails	
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	4			Part V - General Health & Safety Require	28 5 -	-Guardrails	
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	5			Part VI - Occupational Health Requirement	45 8 -	-Ventilation	
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	6			Part VI - Occupational Health Requirement	68 1-b	-Noise hazards	
2015/10/21	POMERLEAU INC.	Muskrat Falls Switchyard	Muskrat Falls, Labrador	Regular Inspection	1010105	7			Part XXII - Access and Egress	458 1-	-Access, egress and movement	
2016/10/18	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Grounding Facility	Indian Head Road, NL	Regular Inspection	671989	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XVI - Traffic Control	373 3-	-Traffic control
2016/10/18	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Grounding Facility	Indian Head Road, NL	Regular Inspection	671989	2			Part VII - Personal Protective Equipment	81 -	-High visibility apparel	
2016/10/18	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Grounding Facility	Indian Head Road, NL	Regular Inspection	671989	3			Workplace Hazardous Materials Information	9 1 -	-Decanted Products	
2016/10/18	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Grounding Facility	Indian Head Road, NL	Regular Inspection	671989	4			Part VI - Occupational Health Requirement	42 11-	-Hazardous substances	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XXVI - Electrical Operations	478 1 -	-Electrical requirements
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	2			Part XV - Rigging	365 -	-Inspection before use	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	3			Part XV - Rigging	366 -	-Storage	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	4			OHS First Aid Regulations	4 4 -	-Duties of employer	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	5			OHS First Aid Regulations	4 3 -	-Duties of employer	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	6			Part III - General Duties	14 2 -	-General duties of employer	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	7			Part III - General Duties	12 1-c	-Occupational health and safety	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	8			Part III - General Duties	12 1-e	-Occupational health and safety	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	9			Part III - General Duties	12 1-e	-Occupational health and safety	
2016/10/19	POWTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	671990	10	Occupational Health and Safety	37-	-Committees			
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	1			Part XII - Powered Mobile Equipment	251 3-	-Operation and maintenance	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	2						
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	3	Smoke-free Environment Act, 2005	4 - 1a	-Prohibition			
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	4			Part XII - Powered Mobile Equipment	267 1-	-Start of shift inspection	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	5			OHS First Aid Regulations	16 -	-#1 First Aid Kit	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	6			Part XX - Fire Prevention & Control	443 1 -	-Fire protection	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	7			Part V - General Health & Safety Require	40 1 -	-Emergency lighting	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	8			Part XXVI - Electrical Operations	478 1 -	-Electrical requirements	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	9	Occupational Health and Safety	38.1 - 1	-Committee training	25 2 -	-Operations of committees,	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	10			Part V - General Health & Safety Require	40 1 -	-Emergency lighting	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	11			Part XXVI - Electrical Operations	481 1-b	-Space around equipment	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	12			Part XXVI - Electrical Operations	480 -	-Service rooms	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	13			Part XXVI - Electrical Operations	478 1 -	-Electrical requirements	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	14			Workplace Hazardous Materials Information	13 2 -	-Supplier Material Safety D	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	15			Part VI - Occupational Health Requirement	63 -a	-Emergency washing facility	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	16			Workplace Hazardous Materials Information	6 1-c	-Instructions To Employees	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	17			Part V - General Health & Safety Require	36 1 -	-Illumination	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	18			Part XX - Fire Prevention & Control	443 1 -	-Fire protection	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	19			Part XV - Rigging	353 1 -	-Open hook restriction	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	20			Part V - General Health & Safety Require	36 1 -	-Illumination	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	21			Part XI - Scaffolds, Stages & Work Platform	151 -	-Inspection	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	22			Part VIII - Machinery and Equipment	88 1-b i	-Safe machinery and equipment	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	23			Part XXVI - Electrical Operations	478 1 -	-Electrical requirements	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	24			Part III - General Duties	14 4 -	-General duties of employer	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	25			Part VI - Occupational Health Requirement	67 -d	-Sanitary and orderly conditions	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	26			Part XX - Fire Prevention & Control	443 1 -	-Fire protection	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	27			Part III - General Duties	14 2 -	-General duties of employer	
2016/12/01	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931860	28			Part III - General Duties	19 1-b	-Co-ordination of work	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931889	1			Part III - General Duties	18 1 -	-Safety inspections	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931889	2			Part VII - Personal Protective Equipment	81 -	-High visibility apparel	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Camp site for Maritime Link Project	Off of the Burgoe Highway, NL	Regular Inspection	931889	3			Part VII - Personal Protective Equipment	74 2 -	-General requirements of safety	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 112	Route 480, Burgoe Highway, NL	Regular Inspection	931892	1			OHS First Aid Regulations	4 3 -	-Duties of employer	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 112	Route 480, Burgoe Highway, NL	Regular Inspection	931892	2	Occupational Health and Safety	5 - a	-Specific duties of employers			
2017/04/11	POWTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931984	1			Part XVIII - Excavation, Underground Work	408 1-b	-Removal of material	
2017/04/11	POWTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931984	2			Part XXII - Access and Egress	458 1-	-Access, egress and movement	
2017/04/11	POWTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931984	3			Part VII - Personal Protective Equipment	74 2 -	-General requirements of safety	
2017/04/11	POWTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931984	4			Part XXVI - Electrical Operations	488 2 -	-Grounding portable low vol	
2017/04/11	POWTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931984	5			OHS First Aid Regulations	16 -	-#1 First Aid Kit	
2016/09/22	POWTEL UTILITIES CONTRACTORS LIMITED	Traffic control	Route 480, Burgoe Highway	Regular Inspection	941490	1			Part XVI - Traffic Control	373 4-	-Traffic control	
2016/09/22	POWTEL UTILITIES CONTRACTORS LIMITED	Traffic control	Route 480, Burgoe Highway	Regular Inspection	941490	2	Occupational Health and Safety	5 - b	-Specific duties of employers			
2016/09/22	POWTEL UTILITIES CONTRACTORS LIMITED	Traffic control	Route 480, Burgoe Highway	Regular Inspection	941490	3	Occupational Health and Safety	26 - 2	-Powers of investigation			
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 115, Structure 202	Route 480, Burgoe Highway, NL	Regular Inspection	941578	1	Occupational Health and Safety	26 - 1b	-Powers of investigation			
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 115, Structure 202	Route 480, Burgoe Highway, NL	Regular Inspection	941578	2			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 115, Structure 202	Route 480, Burgoe Highway, NL	Regular Inspection	941578	3			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 115, Structure 202	Route 480, Burgoe Highway, NL	Regular Inspection	941578	4			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 133	Route 480, Burgoe Highway, NL	Regular Inspection	941579	1			Part VII - Personal Protective Equipment	71 -a	-Selection, use and maintain	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 133	Route 480, Burgoe Highway, NL	Regular Inspection	941579	2			Part VI - Occupational Health Requirement	61 1 -	-Toilet facilities	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 133	Route 480, Burgoe Highway, NL	Regular Inspection	941579	3			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 133	Route 480, Burgoe Highway, NL	Regular Inspection	941580	1			Part XVI - Traffic Control	373 3-	-Traffic control	
2017/01/10	POWTEL UTILITIES CONTRACTORS LIMITED	Access 133	Route 480, Burgoe Highway, NL	Regular Inspection	941580	2	Occupational Health and Safety	26 - 1b	-Powers of investigation			
2017/01/16	POWTEL UTILITIES CONTRACTORS LIMITED	Access 115, Structure 202	Route 480, Burgoe Highway, NL	Follow-up	941584	1	Occupational Health and Safety	27 - 1b	-Stop work orders			
2017/01/16	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Investigate Accident	941587	1	Occupational Health and Safety	26 - 1b	-Powers of investigation	Part X - Fall Protection	139 -	-Training requirement
2017/01/16	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Investigate Accident	941587	2	Occupational Health and Safety	54 - 1a	-Reporting accidents			
2017/01/18	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941588	1	Occupational Health and Safety	27 - 1b	-Stop work orders	Part X - Fall Protection	142 10-a & b	-Fall arrest system
2017/01/18	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941588	2	Occupational Health and Safety	27 - 1b	-Stop work orders	Part XXVI - Electrical Operations	490 1 -	-Isolation and lockout
2017/01/27	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941590	1			Part III - General Duties	14 4 -	-General duties of employer	
2017/01/27	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941590	2	Occupational Health and Safety	5 - b	-Specific duties of employers			
2017/01/27	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941590	3	Occupational Health and Safety	5 - b	-Specific duties of employers			
2017/01/30	POWTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941592	1	Occupational Health and Safety	26 - 1b	-Powers of investigation			

2017/01/31	POWERTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Regular Inspection	941594	1			Part III - General Duties	14 4-	-General duties of employer
2017/01/31	POWERTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Regular Inspection	941594	2			Part III - General Duties	14 4-	-General duties of employer
2017/02/28	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Burgoe Highway, NL	Regular Inspection	941597	0					
2017/03/08	POWERTEL UTILITIES CONTRACTORS LIMITED	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941604	0					
2017/03/09	POWERTEL UTILITIES CONTRACTORS LIMITED	Indian Head	Outside Stephenville Crossing, NL	Follow-up	941611	0					
2017/05/18	POWERTEL UTILITIES CONTRACTORS LIMITED	Tower assembly	Bottom Brook, NL	Investigate Accident	941655	1	Occupational Health and Safety	26 - 2	-Powers of investigation		
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951124	0					
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951125	0					
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951127	1			Part XIV - Cranes, Hoists & Other Lifting	296 1-	-Inspection & maintenance
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951127	2			Part XII - Powered Mobile Equipment	269 -	-Unattended equipment
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951127	3			Part XV - Rigging	365 -	-Inspection before use
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951127	4			Part VIII - Machinery and Equipment	88 1-a	-Safe machinery and equipment
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951127	5			Part VI - Occupational Health Requirement	59 2-a	-Storage of hazardous substance
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951128	1			Part X - Fall Protection	142 1-b ii	-Fall arrest system
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951128	2			Part VI - Occupational Health Requirement	61 2-1	-Toilet facilities
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951128	3			Part XIV - Cranes, Hoists & Other Lifting	296 1-	-Inspection & maintenance
2017/03/22	POWERTEL UTILITIES CONTRACTORS LIMITED	Maritime Link Project	Granite Canal, NL	Regular Inspection	951129	1			Part XVIII - Excavation, Underground Work	408 1-a	-Removal of material
2016/10/17	ROKSTAD POWER	Transmission Tower Installation	Route 408 Cape Ray Access Intersection, NL	Regular Inspection	671984	1			Part XVI - Traffic Control	373 3-	-Traffic control
2016/10/17	ROKSTAD POWER	Transmission Line Installation	Location 230, West of South Branch, NL	Regular Inspection	671985	1			OHS First Aid Regulations	4 4-	-Duties of employer
2016/10/17	ROKSTAD POWER	Transmission Line Installation	Location 230, West of South Branch, NL	Regular Inspection	671985	2			OHS First Aid Regulations	4 3-	-Duties of employer
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	1			Part XVII - Construction, Excavation & D	398 -a	-Hazardous materials
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	2			Part XXII - Access and Egress	458 1-	-Access, egress and movement
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	3			Part V - General Health & Safety Require	386 2-	-illumination
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	4			Part XVI - Electrical Operations	488 1-a	-Space around equipment
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	5			Part XX - Fire Prevention & Control	443 2-	-Fire protection
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	6			Part VI - Occupational Health Requirement	61 2-c	-Toilet facilities
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	7			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	8			Part XV - Rigging	364 -	-Slings standards
2016/12/02	ROKSTAD POWER	Main Office Yard Area	St. Georges, NL	Regular Inspection	672006	9			Part VI - Occupational Health Requirement	61 -d	-Emergency washing facility
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	1	Occupational Health and Safety	27 - 1b	-Stop work orders	406 4-a	-Pre-excavation requirement
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	2			Part XVIII - Excavation, Underground Work	408 1-b	-Removal of material
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	3	Occupational Health and Safety	7 - c	-Specific duties of workers		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	4	Occupational Health and Safety	5 - b	-Specific duties of employers		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	5	Occupational Health and Safety	5 - b	-Specific duties of employers		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	6	Occupational Health and Safety	5 - b	-Specific duties of employers		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 19, Cape Ray, NL	Regular Inspection	931965	7	Occupational Health and Safety	45 - 1a	-Right to refuse to work		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 18, Cape Ray, NL	Regular Inspection	931969	1			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol
2017/04/05	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 18	Regular Inspection	931976	1			Part III - General Duties	14 1-	-General duties of employer
2017/04/05	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE 18	Regular Inspection	931976	2			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/04/05	ROKSTAD POWER	Ground cable installation	Access AT325, Structure SD083	Regular Inspection	931977	1			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol
2017/04/05	ROKSTAD POWER	Ground cable installation	Access AT325, Structure SD083	Regular Inspection	931977	2			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/04/05	ROKSTAD POWER	Ground cable installation	Access AT325, Structure SD083	Regular Inspection	931977	3			Part VI - Occupational Health Requirement	62 1-a	-Washing facilities
2017/06/06	ROKSTAD POWER	Erecting self-supporting tower	Access AT 228	Regular Inspection	932039	1			Part XIV - Cranes, Hoists & Other Lifting	309 2-c	-Operator qualifications
2017/06/06	ROKSTAD POWER	Erecting self-supporting tower	Access AT 228	Regular Inspection	932039	2			Part XIV - Cranes, Hoists & Other Lifting	298 -c	-Certification
2016/11/10	ROKSTAD POWER	Traffic Control	Accesses 105 to 229, TCH	Regular Inspection	941537	1			Part XVI - Traffic Control	373 3-	-Traffic control
2016/11/10	ROKSTAD POWER	Traffic Control	Accesses 105 to 229, TCH	Regular Inspection	941537	2			Part III - General Duties	19 1-b	-Co-ordination of work
2016/12/01	ROKSTAD POWER	Tower assembly	Access road (fly yard) 226	Regular Inspection	941553	1	Occupational Health and Safety	5 - a	-Specific duties of employers		
2016/12/01	ROKSTAD POWER	Tower assembly	Access road (fly yard) 226	Regular Inspection	941553	2			Part VII - Personal Protective Equipment	74 2-	-General requirements of safety
2016/12/01	ROKSTAD POWER	Tower assembly	Access road (fly yard) 226	Regular Inspection	941553	3			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol
2016/12/01	ROKSTAD POWER	Tower assembly	Access road (fly yard) 226	Regular Inspection	941553	4	Occupational Health and Safety	5 - a	-Specific duties of employers		
2016/12/01	ROKSTAD POWER	Tower assembly	Access road (fly yard) 226	Regular Inspection	941553	5			Part III - General Duties	19 1-b	-Co-ordination of work
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	1	Occupational Health and Safety	27 - 1b	-Stop work orders	406 4-a	-Pre-excavation requirement
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	2			Part XVIII - Excavation, Underground Work	408 1-b	-Removal of material
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	3	Occupational Health and Safety	5 - b	-Specific duties of employers		
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	4			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	5			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	6			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941624	7			Part VII - Personal Protective Equipment	74 2-	-General requirements of safety
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941627	1	Occupational Health and Safety	27 - 1b	-Stop work orders	406 4-a	-Pre-excavation requirement
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941627	2			Part XVIII - Excavation, Underground Work	408 1-b	-Removal of material
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941627	3			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941627	4			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities
2017/03/29	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941627	5			Part XXVI - Electrical Operations	488 2-	-Grounding portable low vol
2017/03/29	ROKSTAD POWER	Traffic Control	Access Roads from Bottom Brook to Cape Ray, NL	Regular Inspection	941628	1			Part III - General Duties	18 1-	-Safety inspections
2017/03/29	ROKSTAD POWER	Traffic Control	Access Roads from Bottom Brook to Cape Ray, NL	Regular Inspection	941628	2			Part III - General Duties	18 1-	-Safety inspections
2017/04/05	ROKSTAD POWER	Pull testing anchor rods	Access 334, Tower SE19, Cape Ray, NL	Regular Inspection	941632	0					
2017/04/05	ROKSTAD POWER	Self-supporter foundation install	Access 334, Structure SE17, Cape Ray, NL	Regular Inspection	941633	1			Part XXII - Access and Egress	458 1-	-Access, egress and movement
2017/05/31	ROKSTAD POWER	Traffic Control	Access Roads from Bottom Brook to Cape Ray, NL	Regular Inspection	941663	0					
2017/06/06	ROKSTAD POWER	MLP Project, various	Various Access Roads from Bottom Brook to Cape Ray	Regular Inspection	941667	1			Part XVI - Traffic Control	373 3-	-Traffic control
2017/06/06	ROKSTAD POWER	MLP Project, various	Various Access Roads from Bottom Brook to Cape Ray	Regular Inspection	941667	2			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/06/06	ROKSTAD POWER	MLP Project, various	Various Access Roads from Bottom Brook to Cape Ray	Regular Inspection	941667	3			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities
2017/06/06	ROKSTAD POWER	Stringing operation (Puller)	AT109 (Exit 2 from TCH to Route 490)	Regular Inspection	941670	1	Occupational Health and Safety	5 - d	-Specific duties of employers		
2017/06/06	ROKSTAD POWER	Stringing operation (Puller)	AT109 (Exit 2 from TCH to Route 490)	Regular Inspection	941670	2			Part XII - Powered Mobile Equipment	267 1-	-Start of shift inspection
2017/06/06	ROKSTAD POWER	Stringing Operation	Access Road AT106 off the TCH	Regular Inspection	941671	1	Occupational Health and Safety	5 - d	-Specific duties of employers		
2017/06/06	ROKSTAD POWER	Stringing Operation	Access Road AT106 off the TCH	Regular Inspection	941671	2			Part VI - Occupational Health Requirement	61 1-	-Toilet facilities
2017/06/06	ROKSTAD POWER	Stringing Operation	Access Road AT106 off the TCH	Regular Inspection	941671	3			Part VI - Occupational Health Requirement	62 1-b	-Washing facilities
2017/06/12	ROKSTAD POWER	Report of a tower down	MLP Access Road Right-Of-Way	Investigate Accident	941673	1	Occupational Health and Safety	26 - 2	-Powers of investigation		
2017/06/12	ROKSTAD POWER	Report of a tower down	MLP Access Road Right-Of-Way	Investigate Accident	941673	2					
2015/06/02	SAFETY FIRST CONTRACTING (1995) LTD.	Dowdens Point	Seal Cove Road and Lears Road, Conception Bay South	Regular Inspection	720056	1			Part III - General Duties	14 1-	-General duties of employer
2015/06/02	SAFETY FIRST CONTRACTING (1995) LTD.	Dowdens Point	Seal Cove Road and Lears Road, Conception Bay South	Regular Inspection	720056	2			Part XVI - Traffic Control	373 3-	-Traffic control
2015/06/05	SAFETY FIRST CONTRACTING (1995) LTD.	Dowdens Point	Seal Cove Road and Lears Road, Conception Bay South	Follow-up	720057	0			Part XVI - Traffic Control	373 3-	-Traffic control
2014/04/30	SAFETY FIRST CONTRACTING (1995) LTD.	Trans-Canada Highway	Divided Highway near Soldiers Pond, NL	Regular Inspection	1010046	0					
2013/11/27	SPRINGDALE FOREST RESOURCES LTD	Main camp and maintenance area	65 KM West of Happy Valley-Goose Bay, NL	Regular Inspection	501069	1			Part VIII - Machinery and Equipment	89 -b	-General requirements
2013/11/27	SPRINGDALE FOREST RESOURCES LTD	Main camp and maintenance area	66 KM West of Happy Valley-Goose Bay, NL	Regular Inspection	501069	2			Part VI - Occupational Health Requirement	42 11-	-Hazardous substances
2017/01/19	SPRINGDALE FOREST RESOURCES LTD	TCH - Divided Highway - West Lanes	Holyrood Access area near entrance to Rod and Gun Club	Regular Inspection	640946	1	Occupational Health and Safety	10 -	-Duty of principal contractor		

2016/10/27	SPRINGDALE FOREST RESOURCES LTD	Quarry	Entrance, Catamaran Park Rd, Nalcor Transmission Line Project	Regular Inspection	661822	0					
2017/03/07	SPRINGDALE FOREST RESOURCES LTD	Access Road Construction	Str 55-406, 55-419, Ocean Pond, NL	Regular Inspection	672025	0					
2015/09/10	SPRINGDALE FOREST RESOURCES LTD	Hydro Transmission Line Access Road	Eagle Mountain Road, Taylor's Brook Road, Sop's Arm, NL	Investigate Accident	901535	1	Occupational Health and Safety	10 -	-Duty of principal contractor		
2015/09/10	SPRINGDALE FOREST RESOURCES LTD	Hydro Transmission Line Access Road	Eagle Mountain Road, Taylor's Brook Road, Sop's Arm, NL	Investigate Accident	901535	2				Part III - General Duties	14 2 - - General duties of employer
2017/04/11	STANTEC CONSULTING LTD	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	931985	0					
2017/03/08	STARK INTERNATIONAL	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941613	1				Part VII - Personal Protective Equipment	81 - - High visibility apparel
2017/03/08	STARK INTERNATIONAL	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941613	2				Part XXII - Access and Egress	460 1-a - -Stairs
2017/03/08	STARK INTERNATIONAL	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941613	3				Part V - General Health & Safety Require	30 2 - -Openings, pits and tanks
2017/03/08	STARK INTERNATIONAL	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941613	4				Part VI - Occupational Health Requirement	68 5 - -Noise hazards
2017/03/08	STARK INTERNATIONAL	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941613	5				Part VI - Occupational Health Requirement	67 -d - -Sanitary and orderly conditions
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	1				Part XXI - Welding, Burning & Cutting Op	454 - -Ventilation
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	2				Part XXI - Welding, Burning & Cutting Op	457 - -Respiratory protection
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	3				Part VI - Occupational Health Requirement	68 1-b - -Noise hazards
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	4				Part VI - Occupational Health Requirement	68 1-a - -Noise hazards
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	5				Part VI - Occupational Health Requirement	45 1-b - -Ventilation
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	6				Part XVII - Construction, Excavation & D	398 -a - -Hazardous materials
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	7				Part XXVI - Electrical Operations	478 1 - -Electrical requirements
2014/05/29	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671657	8				Part VI - Occupational Health Requirement	45 7-a - -Ventilation
2015/02/04	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671726	1				Part IX - De-Energization and Lockout	128 - -General requirement
2015/02/04	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671726	2				Part V - General Health & Safety Require	36 2 - -Illumination
2015/02/04	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671726	3				Part XV - General Health & Safety Require	31 1 - -Material storage
2015/07/22	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671781	1				Part XV - Rigging	353 1 - -Open hook restriction
2015/07/22	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671781	2				Part XXI - Welding, Burning & Cutting Op	449 1-a - -Gas welding and burning
2015/07/22	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671781	3				Part VIII - Machinery and Equipment	97 -a - -Restraining devices
2015/07/22	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671781	4				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2015/07/22	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	671781	5				Part XXII - Access and Egress	459 1 - -Exits and doors
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	1				Part VI - Occupational Health Requirement	42 7-c - -Hazardous substances
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	2				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	3				Part VII - Personal Protective Equipment	85 3 - -Respiratory protection equip
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	4				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	5				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	6				Part VI - Occupational Health Requirement	45 1-c - -Ventilation
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	7				Part XXI - Welding, Burning & Cutting Op	456 - -Receptacles for stubs
2014/11/05	TALON ENERGY SERVICES INC.	Fabrication Facility	Port aux Basques, NL	Regular Inspection	830345	8				Part VI - Occupational Health Requirement	68 3-b - -Noise hazards
2017/03/17	TALON ENERGY SERVICES INC.	Soliders Pond	TCH East of Butterport Park Interchange	Regular Inspection	1010147	0					
2016/06/30	TRISTRAR MECHANICAL LTD	Condenser Bldg	Soliders Pond, NL	Regular Inspection	671936	1				Part V - General Health & Safety Require	36 1 - -Illumination
2016/06/30	TRISTRAR MECHANICAL LTD	Condenser Bldg	Soliders Pond, NL	Regular Inspection	671936	2				Part VI - Occupational Health Requirement	68 1-b - -Noise hazards
2016/06/30	TRISTRAR MECHANICAL LTD	Condenser Bldg	Soliders Pond, NL	Regular Inspection	671936	3				Part III - General Duties	14 1 - -General duties of employer
2016/06/30	TRISTRAR MECHANICAL LTD	Condenser Bldg	Soliders Pond, NL	Regular Inspection	671936	4				Part VII - Personal Protective Equipment	74 1 - -General requirements of safety
2016/06/30	TRISTRAR MECHANICAL LTD	Condenser Bldg	Soliders Pond, NL	Regular Inspection	671936	5				Part VII - Personal Protective Equipment	75 - -Eye and face protection
2015/03/18	VALARD CONSTRUCTION LP	DC - Transmission Line	23 Km Access Road, Near Forteau, NL	Regular Inspection	501222	1				Part XXII - Access and Egress	458 2 - -Access, egress and movement
2015/03/18	VALARD CONSTRUCTION LP	DC - Transmission Line	23 Km Access Road, Near Forteau, NL	Regular Inspection	501222	2				Part III - General Duties	14 4 - -General duties of employer
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	1				Part XXVIII - General Mining Requirement	536 1-a - -Wheel chocks
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	2				Part XXII - Access and Egress	458 6 - -Access, egress and movement
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	3				Part V - General Health & Safety Require	31 1 - -Material storage
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	4				Part VI - Occupational Health Requirement	61 1 - -Toilet facilities
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	5				Part VI - Occupational Health Requirement	62 1-a - -Washing facilities
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	6				Part VI - Occupational Health Requirement	63 -a - -Emergency washing facility
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	7				Workplace Hazardous Materials Information	9 1 - -Decanted Products
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	8				Part XV - Rigging	365 - -Inspection before use
2016/10/20	VALARD CONSTRUCTION LP	STR. S4, 132 - 142	Lynx Pond Road - Birch area, West of Deer Lake	Regular Inspection	501493	9				Part III - General Duties	12 1-c - -Occupational health and safety
2016/10/27	VALARD CONSTRUCTION LP	Sand/Gravel Quarry	Dawe's Pond Rd, Near Branch 2	Regular Inspection	661821	1				Part XVIII - Excavation, Underground Work	409 1-b - -Faces and slopes
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	1				Part VI - Occupational Health Requirement	68 1-b - -Noise hazards
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	2				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	3				Part VII - Personal Protective Equipment	83 - -Respiratory protection pro
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	4				Part XVIII - Excavation, Underground Work	410 1 - -Excavation safety
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	5	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XIX - General Blasting	427 2 - -Storage and handling
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	6				Part XXVI - Electrical Operations	488 2 - -Grounding portable low vol
2016/10/27	VALARD CONSTRUCTION LP	Drill and Blasting Site	Structure 290, Dawes Pond Road, Nalcor Transmission Line	Regular Inspection	661823	7				Part IX - De-Energization and Lockout	128 - -General requirement
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part XXVII - Excavation, Underground Work	406 4-a - -Pre-excavation requirement
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	2	Occupational Health and Safety	5 - b	-Specific duties of employers		
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	3				Part XVIII - Excavation, Underground Work	410 1 - -Excavation safety
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	4				Part XXVI - Electrical Operations	488 2 - -Grounding portable low vol
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	5				Part XVIII - Excavation, Underground Work	408 1-b - -Removal of material
2016/10/27	VALARD CONSTRUCTION LP	Tower Foundation Installation	Structure 370, Catamaran Road, Nalcor Transmission Line	Regular Inspection	661824	6	Occupational Health and Safety	5.1 -	-Supervisors' general duty		
2014/07/03	VALARD CONSTRUCTION LP	Truck/Trailer/Worker Contact	Lower Churchill Project, Churchill Falls, NL	Regular Inspection	671667	1	Occupational Health and Safety	54 - 1b	-Reporting accidents		
2014/07/08	VALARD CONSTRUCTION LP	Transmission Tower Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671670	0					
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	1				Part XX - Fire Prevention & Control	443 1 - -Fire protection
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	2				Part V - General Health & Safety Require	39 3 - -Emergency procedures
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	3				Part XVIII - Excavation, Underground Work	410 1 - -Excavation safety
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	4				Part XVIII - Excavation, Underground Work	407 2-c - -Excavation or access
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	5				Part III - General Duties	14 4 - -General duties of employer
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	6				Part XII - Powered Mobile Equipment	269 - -Unattended equipment
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	7				Part XXVI - Electrical Operations	478 1 - -Electrical requirements
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	8				Part IX - De-Energization and Lockout	128 - -General requirement
2015/01/29	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Regular Inspection	671724	9				Part XII - Powered Mobile Equipment	269 - -Unattended equipment
2015/02/13	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Follow-up	671728	1				Part XVIII - Excavation, Underground Work	410 1 - -Excavation safety
2015/02/13	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Follow-up	671728	2				Part XVIII - Excavation, Underground Work	410 3 - -Excavation safety
2015/02/13	VALARD CONSTRUCTION LP	DC Transmission Line Installation	Lower Churchill Project, Happy Valley-Goose Bay, NL	Follow-up	671728	3				Part III - General Duties	12 2-b iii - -Occupational health and safety
2015/03/18	VALARD CONSTRUCTION LP	Workshop/Hanger	Forteau, NL	Regular Inspection	671735	1				Part XXVI - Electrical Operations	478 1 - -Electrical requirements
2015/03/18	VALARD CONSTRUCTION LP	Workshop/Hanger	Forteau, NL	Regular Inspection	671735	2				Part XX - Fire Prevention & Control	443 2 - -Fire protection
2015/03/18	VALARD CONSTRUCTION LP	Workshop/Hanger	Forteau, NL	Regular Inspection	671735	3				Part VIII - Machinery and Equipment	89 -b - -General requirements
2015/03/18	VALARD CONSTRUCTION LP	Workshop/Hanger	Forteau, NL	Regular Inspection	671735	4				Part VI - Occupational Health Requirement	45 2 - -Ventilation
2015/03/18	VALARD CONSTRUCTION LP	Workshop/Hanger	Forteau, NL	Regular Inspection	671735	5				Part VI - Occupational Health Requirement	42 1 - -Hazardous substances
2015/03/18	VALARD CONSTRUCTION LP	Camp 3 Installation	L'ance au Loup, NL	Regular Inspection	671736	1				Part XVII - Construction, Excavation & D	377 5 - -Temporary floors

2016/11/10	VOLTAGE POWER LTD.	Access road construction	Access road 309, TCH	Regular Inspection	941541	5			Part XV - Rigging	365	-	-	-Inspection before use	
2016/12/01	VOLTAGE POWER LTD.	Traffic Control	Access 315, TCH	Regular Inspection	941555	0								
2016/12/08	VOLTAGE POWER LTD.	Foundation installation	Structure 57, Doyles, NL	Regular Inspection	941559	1			Part XXI - Welding, Burning & Cutting Op	450	1-a	ii	-Compressed gas cylinders	
2016/12/08	VOLTAGE POWER LTD.	Tower assembly	Access road AT320, structure 47	Regular Inspection	941560	1			Part VI - Occupational Health Requirement	68	1-b	-	-Noise hazards	
2017/04/05	VOLTAGE POWER LTD.	Tower assembly	Access AT305, Structure SC124	Regular Inspection	941635	1			Part XXVI - Electrical Operations	488	2-	-	-Grounding portable low vol	
2017/04/05	VOLTAGE POWER LTD.	Tower assembly	Access AT305, Structure SC124	Regular Inspection	941635	2			Part XXI - Welding, Burning & Cutting Op	450	1-a	ii	-Compressed gas cylinders	
2017/04/05	VOLTAGE POWER LTD.	Tower assembly	Access AT305, Structure SC124	Regular Inspection	941635	3			Part XV - Rigging	365	-	-	-Inspection before use	
2017/04/05	VOLTAGE POWER LTD.	Tower assembly	Access AT305, Structure SC124	Regular Inspection	941635	4	Occupational Health and Safety	26 - 1b	-Powers of investigation					
2017/06/06	VOLTAGE POWER LTD.	Erecting Self-Supporting Tower	Access AT228, Structure SC083N	Regular Inspection	941668	1			Part VII - Personal Protective Equipment	74	2-	-	-General requirements of safety	
2016/04/26	WEST COAST EXCAVATING & EQUIPMENT	Turn table construction	15-25 Riverside Drive, Corner Brook, NL	Regular Inspection	931586	0								
2016/12/15	WESTWARD INDUSTRIAL INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941572	1			Part XI - Scaffolds, Stages & Work Platform	205	-	-	-Shift inspection	
2016/12/15	WESTWARD INDUSTRIAL INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941572	2			Part VII - Personal Protective Equipment	71	-a	-	-Selection, use and maintain	
2017/03/08	WESTWARD INDUSTRIAL INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941600	1			Part VI - Occupational Health Requirement	67	-d	-	-Sanitary and orderly conditions	
2017/04/11	WESTWARD INDUSTRIAL INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941641	1			Part VI - Occupational Health Requirement	68	1-b	-	-Noise hazards	
2017/04/11	WESTWARD INDUSTRIAL INC.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941641	2			Part XXI - Welding, Burning & Cutting Op	450	1-a	ii	-Compressed gas cylinders	
2015/08/04	WOODWARDS LIMITED	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Regular Inspection	671794	1	Occupational Health and Safety	27 - 1a	-Stop work orders	Part VIII - Machinery and Equipment	89	-a	-	-General requirements
2015/08/04	WOODWARDS LIMITED	Lower Churchill Development	Happy Valley-Goose Bay, NL.	Follow-up	671796	0								
2017/03/08	YOUNG'S INDUSTRIAL REFRIGERATION LTD.	HVDC Converter Station, MLP	Bottom Brook, NL	Regular Inspection	941602	1			Part XI - Scaffolds, Stages & Work Platform	161	1-	-	-Guardrails and toeboards	